

RECEIVED

Form 3160-5
(March 2012)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

MAR 08 2013

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELL ABANDONMENT
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. **SF-079367-A**
NM-NM78406 / NMSE 0739367
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

Oil Well Gas Well Other

2. Name of Operator
Chevron Midcontinent L.P.

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
Rincon 125M

3a. Address
ATTN: Regulatory Specialist
332 Road 3100 Aztec New Mexico 87410

3b. Phone No. (include area code)
505-333-1941

9. API Well No.
30-039-25181

10. Field and Pool or Exploratory Area
Basin Dakota/Blanco Mesaverde

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1800 FNL 1700 FWL F-26-27N-06W

11. County or Parish, State
Rio Arriba County, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

Notice of Intent

Acidize

Deepen

Production (Start/Resume)

Water Shut-Off

Alter Casing

Fracture Treat

Reclamation

Well Integrity

Subsequent Report

Casing Repair

New Construction

Recomplete

Other Replace

Final Abandonment Notice

Change Plans

Plug and Abandon

Temporarily Abandon

Separator

Convert to Injection

Plug Back

Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Scheduled to begin March 20, 2013.

1. Shut in the location and blow down the existing separator
2. Confirm positive isolation
3. Drain and clean the existing separator
4. Disconnect all piping from existing separator
5. Test existing separator for NORM, lead paint, and asbestos
6. Remove existing separator from location and transport to scrap or surplus storage
7. Transport replacement separator to location and position in place
8. Modify appropriate piping and prepare for connections
9. Make vessel piping connections
10. Complete Pre Startup Safety Review
11. Purge vessel and start up location

RCVD MAR 19 '13

OIL CONS. DIV.

DIST. 3

See attached photos of current separator and proposed new smaller separator.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

April E. Pohl

Title Regulatory Specialist

Signature

April E Pohl

Date

March 7, 2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Mark Kelly

Title

ENVIRONMENTAL
COMPLIANCE TEAM LEAD

Date

3-12-13

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

WASHINGTON

AMOD ea