

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0135  
Expires: July 31, 2010

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

5. Lease Serial No.  
NMNM99705

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

**SUBMIT IN TRIPLICATE - Other instructions on reverse side.**

1. Type of Well  
 Oil Well  Gas Well  Other

8. Well Name and No.  
EAGLE SPRINGS 8 FED 1

2. Name of Operator  
HIGH PLAINS OPERATING CO LLC  
Contact: BUTCH BUTLER  
E-Mail: bbutler@highplainsop.com

9. API Well No.  
30-043-20949-00-S1

3a. Address  
BUENA VISTA, NM 81211

3b. Phone No. (include area code)  
Ph: 719-395-8059

10. Field and Pool, or Exploratory  
WILDCAT

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Sec 8 T19N R4W NWNE 263FNL 2545FEL

11. County or Parish, and State  
SANDOVAL COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Workover Operations
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

HPOC, LLC is operating with Bond No. NMB 000457.

HPOC reperforated the Entrada formation thru cemented-in drill string. The formation was originally perforated on May 22, 2010 over the following intervals: 5975 ft to 5995 ft; 6005 ft to 6025 ft; 6041 ft to 6061 ft (4 spf, .27 inch EHD, 20 inch est depth of Pen). This was a total of 60 ft of perforations over the 86 ft interval from 5975 ft to 6061 ft.

Jan. 25, 2013. MIRU Hurricane Well Service. TIH on 157 jts of 3 1/2 inch tubing and alignment tool, rotated tbg and alignment tool fell over cemented 3 1/2 inch tubing/fish looking up. SDFWE and frigid temps.

RCVD JUL 25 '13  
OIL CONS. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #213639 verified by the BLM Well Information System  
For HIGH PLAINS OPERATING CO LLC, sent to the Rio Puerco  
Committed to AFMSS for processing by WILLIAM TAMBEKOU on 07/23/2013 (10JXL0005SE)**

Name (Printed/Typed) BUTCH BUTLER	Title MANAGER
Signature (Electronic Submission)	Date 07/16/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By <b>ACCEPTED</b>	WILLIAM TAMBEKOU Title PETROLEUM ENGINEER	Date 07/23/2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office Rio Puerco		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***



**Additional data for EC transaction #213639 that would not fit on the form**

**32. Additional remarks, continued**

Jan. 29, 2013. PU Maverick coil tubing and RIH to re-perforate Entrada through stuck drill string. Made 3 gun runs on coil tbg and perforated from 6000 ft to 6059 ft (6spf, 0.24 inch EHD, 23.6 inch EPD).

Jan. 30, 2013. Made 6 gun runs on coil tbg and perforated from 5880 ft to 6000 ft (6spf, 0.24 inch EHD, 23.6 inch EPD). Total perforations over the past 2 days are from 5880 ft to 6059 ft, a total of 179 ft.

Jan. 31, 2013. RIH with nozzle on coil tbg to btm, circulated N2 and cleaned out hole. Fluid entry at 37 bbls/hour. Recovered light fine sand with skim of oil. RD and release coil unit.

Feb. 1, 2013. Completed TOH with 3 1/2 inch tbg and alignment tool. ND BOP & NU wellhead. Shut in well. Plan to return after disposal facilities are placed to run pump.