Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

F	•	/ 1					
Ĺ	.1		١.	Ŧ		,	,

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

DEC 31 2015. Lease Serial No.

NMNM 112953

Water Disposal

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Lybrook E27-2306 03H Oil Well Gas Well Other 2. Name of Operator Encana Oil & Gas (USA) Inc. 9. API Well No. 30-043-21150 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 370 17th Street, Suite 1700 Denver, CO 80202 Counselors Gallup-Dakota 720-876-3437 Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Sandoval County, New Mexico BHL: 1730' FNL and 660' FWL Section 28, T23N, R6W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Other Plugback Casing Repair New Construction Recomplete ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones, Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug Back

Spotted kick plug using the following procedure 12/14/2013.

1. Tripped in hole with open-ended 4 inch drill pipe to 4,900 ft. TVD

2. Pumped high viscosity spacer pill to serve as base for cement kickoff plug

3. Pulled drill string to point just above base of cement plug and circulate bottoms up

Convert to Injection

4. Spotted 400 ft. kickoff plug at 4,900 ft. to 4500 ft. TVD.

a. 197sx of Class G cement with salt (1.15ft3/sk yield, 15.8ppg)

b. Spot tuned spacers

5. Pull drill pipe slowly while reverse circulating

6. Wait 24 hours for cement to cure

Final Abandonment Notice

7. Trip in hole, tagged weak cement at 4435 ft.

8. Drilled from 4435 ft. to 4766 ft. (solid cement around 4,550 ft.)

RCVD JAN 29 '14 OIL CONS. DIV. DIST. 3

9. Started building kickoff trough at 4,766 and time drilled cement plug from 4766 ft. until we jumped the plug at 4787 ft. -- actual kickoff point.

14. Thereby certify that the foregoing is true and correct. Name (Printed/Typed) Amanda Cavoto	Engine guing To charalagist				
Attanda Cavolo	Engineering Technologist				
Signature Manda (and) Date	: 12/30/12				
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE	ACCEPTED FOR RECORD			
Approved by	Title	Date JAN 02 2813 2014			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	FARMINGTON FIELD OFFICE BY:			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction