

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

AUG 21 2014

SUBMIT IN TRIPLICATE - Other instructions on reverse side

15. Lease Serial No.
I-149-IND-7971

6. If Indian, Allottee or Tribe Name
Navajo allotment

7. If Unit or CA/Agreement, Name and/or No.
N/A

8. Well Name and No.
Buena Suerte 29M #1T

9. API Well No.
30-045-32649

10. Field and Pool, or Exploratory Area
Basin Fruitland Coal

11. County or Parish, State
San Juan County, NM

1. Oil Well Gas Well Other

2. Name of Operator
Elm Ridge Exploration Company, LLC

3a. Address
PO Box 156 Bloomfield, NM 87413

3b. Phone No. (include area code)
505-632-3476 ext. 201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1785' FNL X 1195' FWL
"E" Sec. 29-T26N-R11W

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Alter Casing
	<input type="checkbox"/> Fracture Treat
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Change Plans
	<input checked="" type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Convert to Injection
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Other _____

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

RCVD SEP 2 '14

Elm Ridge Exploration Co., LLC requests permission to plug and abandon the following well according to the attached procedure. OIL CONS. DIV.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

Notify NMOCD 24 hrs prior to beginning operations

DIST. 3

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed) Amy Archuleta Title Sr. Regulatory Supervisor

Signature *[Signature]* Date August 18, 2014

THIS SPACE FOR FEDERAL OR STATE USE

Approved by Troy Salvess Title Petroleum Eng. Date 8/29/2014

Office FFO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD 14

Elm Ridge Resources

Pertinent Data Sheet

Well Name: Buena Suerte 29M #1T
Footage: 1785' FNL and 1195' FWL
Location: SWNW Section 29, T26N, R11W
County: San Juan County, NM
API#: 30-045-32649

Field: Basin Fruitland Coal

Elevation: 6117' KB

TD: 1401' KB

Completed: 05/15/2007

Casing Record:

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
8-3/4"	7"	20#	J-55	134'	55 sx (Circ. to surface)
7-7/8"	4-1/2"	10.5#	J-55	1397'	110 sx (Circ. to surface)

Tubing: 2-3/8" tubing set at 1276'

Formation Tops:

Nacimiento Surface
Ojo Alamo 275'
Kirtland 372'
Fruitland 1078'
Pictured Cliffs 1247'

Perforations:

Fruitland perforations: 1214'-1234'

Notes:

Wellbore Diagram
Buena Suerte 29M #1T
SWNW Sec. 29, T26N, R11W
San Juan County, NM
API #30-045-32649

Before

Nacimiento - surface



8-3/4" OH
7" 20# J-55 set @ 134'
Circulated cmt to surface

Ojo Alamo - 275'

Kirtland - 372'

Fruitland - 1078'

Pictured Cliffs - 1247'


2-3/8" tbq set at 1276'
Fruitland perforations: 1214'-1234'

7-7/8" OH
4-1/2" 10.5# J-55 set @ 1397'
Circulated cmt to surface
TD: 1401'

Wellbore Diagram
Buena Suerte 29M #1T
SWNW Sec. 29, T26N, R11W
San Juan County, NM
API #30-045-32649

After

Nacimiento - surface




8-3/4" OH
7" 20# J-55 set @ 134'
Circulated cmt to surface

Ojo Alamo - 275'

Kirtland - 372'

Fruitland - 1078'

Pictured Cliffs - 1247'



Fruitland perforations: 1214'-1234'

7-7/8" OH
4-1/2" 10.5# J-55 set @ 1397'
Circulated cmt to surface
TD: 1401'

Buena Suerte

Plugging Program for Bisti 29M #1T

- 1) MOL RU. TOOH with 2-3/8" tubing.
- 2) PU and TIH with 4-1/2" retainer to 1210'. Squeeze below retainer with 12 sx cmt.
- 3) Sting out, mix and pump 95 sx, or sufficient volume, to bring cement to surface inside 4-1/2" casing.
- 4) Cut off well head 4 feet below surface and remediate location in accordance with regulatory agencies' conditions of approval.

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: Buena Suerte 29M #1T

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.