

PN (RBDMS)

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II


P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088



<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>WELL API NO. 30-031-20733</p>
<p>1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/></p>
<p>2. Name of Operator ROBERT L. BAYLESS</p>		<p>6. State Oil & Gas Lease No. LH-3667</p>
<p>3. Address of Operator P.O. BOX 168 FARMINGTON, NM 87499</p>		<p>7. Lease Name or Unit Agreement Name STATE</p>
<p>4. Well Location Unit Letter M : 990 Feet from the SOUTH Line and 990 Feet from The WEST Line Section 16 Township 16N Range 6W NMPM McKINLEY County</p>		<p>8. Well No. 4</p>
<p>10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6564 GL</p>		<p>9. Pool name or Wildcat North Miguel Creek Field</p>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Robert L. Bayless plugged and abandoned this well 6/2/03. The procedure is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom McCarthy TITLE ENGINEER DATE 6/19/03

TYPE OR PRINT NAME Tom McCarthy TELEPHONE NO. (505) 327-2659

(This space for State Use) H. J. Illman TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3 DATE DEC 20 2005

CONDITIONS OF APPROVAL, IF ANY:

12-20-05

Robert L. Bayless
Plug and Abandon Report

State No. 4

990' FSL & 990' FWL, Section 16, T16N, R6W

McKinley County, NM

6/2/2003: Rig up JC Well Service. Trip out with rods and pump. Trip in tubing and tag PBD at 1201'. Roll hole with water. Mix and spot 23 sack bottom plug at 1201'. Trip out tubing and WOC. Trip in and tag plug at 1067'. Trip to 50' and spot 6 sack surface plug. Rigged down. Class B cement was used.

Top off cement in both casings. Installed abandonment marker and backfilled pit. Cleaned up location.