New Mexico Energy Minerals and Natural Resources Department

Form C-140 Revised 06/99

<u>District I</u> - (505) 393-6161 1625 N. French Dr, Hobbs, NM 88240 <u>District II</u> - (505) 748-1283 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> - (505) 334-6178 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> - (505) 476-3440

1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, New Mexico 87505 (505) 476-3440

SUBMIT ORIGINAL PLUS 2 COPIES TO APPROPRIATE DISTRICT OFFICE

APPLICATION FOR WELL WORKOVER PROJECT

Burlington Resources C Box 4289, Farmington, Contact Party Maralene Spawn Property Name SAN JUAN 27-5 UNIT UL Section Township Range Fee C 17 27 N 5 W II. Workover Date Workover Commenced 04/27/2005 Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for V. AFFIDAVIT:			
Property Name SAN JUAN 27-5 UNIT UL Section Township Range Fee C 17 27 N 5 W II. Workover Date Workover Commenced 04/27/2005 Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for			OGRID Number 014538
SAN JUAN 27-5 UNIT UL Section Township Range Fee C 17 27 N 5 W II. Workover Date Workover Commenced 04/27/2005 Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for			Phone 505/326-9700
C 17 27 N 5 W II. Workover Date Workover Commenced 04/27/2005 Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for	Well Num	ber	API Number 3003926594
C 17 27 N 5 W II. Workover Date Workover Commenced 04/27/2005 Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for	t From The	Feet From The	County
Date Workover Commenced 04/27/2005 Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for	380 FNL	2310 FWL	RIO ARRIBA
Date Workover Completed: 05/19/2005 III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production for		<u></u>	
III. Attach a description of the Workover IV. Attach a production decline curve or at least three months of production fo	Previous Producing Poo	il(s) (Prior to Workover):	The state of the s
IV. Attach a production decline curve or at least three months of production for			gyra
I have made, or caus available for this Well	authorized representated to be made, a dilige . byledge, this application	orn, upon oath states: tive of the Operator, of the a ent search of the production o n and the data used to prepa	records reasonably
Signature <u>Maleur</u> SUBSCRIBED AND SWORN TO be	Saw Title Sr	Accountant Date ///any of, Notary Public	tricia L. Chiga
FOR OIL CONSERVATIONDIVISION US IV. CERTIFICATION OF APPROVA This Application is hereby approve Division hereby verifies the data sl Secretary of the Taxation and Reve was completed 05-19, 20	L: ed and the above-reference hows a positive produce enue Department of the	enced well is designated a Vertion increase. By copy here is Approval and certifies the	Vell Workover Project and the eof, the Division notifies the

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT:

R

114F

3003926594

	BASIN DAKOTA	BLANCO MESAVERDE	
REG_DTL_D			
05/01/2004	6679		
06/01/2004	6786		
07/01/2004	4141		
08/01/2004	3240		
09/01/2004	4294		
10/01/2004	4358		
11/01/2004	4122		
12/01/2004	4997		
01/01/2005	4704		
02/01/2005	4490		
03/01/2005	5673		
04/01/2005	2045		
05/01/2005	3485	3483	
06/01/2005	11939	11939	
07/01/2005	10739	10739	
08/01/2005	8908	8908	

Thursday, October 27, 2005

QUALIFY: Y MAY 2005

γ

submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

<u>. </u>	_
tu tu	5 JUN 24 P 5. Lease Number
	RECEIVED NMSF-079392
Type of Well	O70 FARMINGTO Tribe Name
GAS	OTO PARMINGTO Pribe Name
Name of Operator	7. Unit Agreement Name
BURLINGTON	
RESCURCES OIL & GAS COMPANY LP	San Juan 27-5 Unit
	8. Well Name & Number
Address & Phone No. of Operator	#114F
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.
Location of Well, Footage, Sec., T, R, M	30-039-26594
	10. Field and Pool
380' FNL & 2310' FWL, Sec. 17, T27N, R5W, NMPM	Blanco MV/Basin DK
	11. County and State Rio Arriba Co., NM
Final Abandonment Altering Casing Conversion to Injection	
3. Describe Proposed or Completed Operations	21 N 7
/28/05 MIRU Aztec #449. ND WH, NU BOP, TOOH w/tbg. RU WL & RIH w/4-1/2" CI	DD & set @ 7500' DD W/ Load hole
/H2O & PT to 3200 psi/good test. ND BOP, NU frac valve. PT casing & valve to 3000#/C	OK. 5/2/05 Perforated Pt. Lookout &
villo & ri to blood psygood test. Indidor, indilitae valve. Pi casing & valve to bloom/C	07' 17' 25' 28' 40' 50' 60' 64' 70'
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05',	(m./1016 bbls 60 April 12 Clister 12 Control
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', i', 97'@ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd	w/1016 bbls 60 Quality Slickwater foam
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97'@ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd f	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU &
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd/100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 (U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & fled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve &
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 (U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lc T-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46',	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & fled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06'.
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd/100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 [U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo T-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hole	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd/100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 (U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lc T-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & fled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 [U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lot-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hole w/2. 3/2', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hole w/2. 3/2', 41', 49', 51', 55', 62', 79', 85', 5210', 51', 51', 51', 51', 51', 51', 51', 51	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew ad hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH leck. RD & released rig @ 1700 hrs 5/19/05.
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 [U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo T-OK. RU WL & perforated Upper Menefee & Clifthouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @ /2-3/8", 4.73 tbg (246 jts) and set @ 7692' w/SN @ 7689'. ND BOP, NU WH. Pumped cl	l w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew ad hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH leck. RD & released rig @ 1700 hrs 5/19/05.
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 [U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lot T-OK. RU WL & perforated Upper Menefee & Clifthouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @ /2-3/8", 4.73 tbg (246 jts) and set @ 7692' w/SN @ 7689'. ND BOP, NU WH. Pumped cl	I w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH neck. RD & released rig @ 1700 hrs 5/19/05.
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd //100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" IU BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 IU 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi lean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo T-OK. RU WL & perforated Upper Menefee & Clifthouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @ 1/2-3/8", 4.73 tbg (246 jts) and set @ 7692' w/SN @ 7689'. ND BOP, NU WH. Pumped cl	I w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH neck. RD & released rig @ 1700 hrs 5/19/05.
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" IU BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 (U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo T-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @ 1/2-3/8", 4.73 tbg (246 jts) and set @ 7692' w/SN @ 7689'. ND BOP, NU WH. Pumped cl. All hereby certify that the foregoing is true and correct. Igned Patsy Clugston Title Sr.	I w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH neck. RD & released rig @ 1700 hrs 5/19/05.
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 [U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo T-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @ 1/2-3/8", 4.73 tbg (246 jts) and set @ 7692' w/SN @ 7689'. ND BOP, NU WH. Pumped cl. A. I hereby certify that the foregoing is true and correct. Igned Patsy Clugston Title Sr. This space for Federal or State Office use) PPROVED BY Title	W/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH neck. RD & released rig @ 1700 hrs 5/19/05. METHON METHON O SC
ower Menefee @ 5392', 5438', 43', 5502', 39', 49', 63', 67', 74', 81', 92', 5601', 03', 05', 5', 97' @ 1 spf = 25 holes. POOH. RD WL. 5/5/05 Acidized w/10 bbls 15% HCL & frac'd /100,000# 20/40 Arizona sand. Used 1,155,000 scf N2 also. RU WL & tried to set 4-1/2" U BOP. RIH w/gauge ring, tagged up @ liner top, flow frac back thru choke 4 days. 5/9/0 [U 4-1/2" impression block. TIH & tagged up @ TOL. TOOH w/block. RIH w/mill & mi ean. TOOH w/mill. RU WL & RIH w/4-1/2" CIBP & set @ 5340'. POOH & LD WL. Lo T-OK. RU WL & perforated Upper Menefee & Cliffhouse @ 1 spf. 4985', 98', 5024', 46', 2', 17', 32', 41', 49', 51', 55', 62', 79', 85', 5220', 38', 61', 79', 94', 5310', Total = 28 hol 5% HCL & frac'd w/12,000 gal 60 Quality Slickwater foam pad & 100,00# 20/40 AZ sand. D frac equip. & started FB. FB for 6 days. 5/17/05 TIH w/mill & milled out FP & CIBP @ 1/2-3/8", 4.73 tbg (246 jts) and set @ 7692' w/SN @ 7689'. ND BOP, NU WH. Pumped cl. A. I hereby certify that the foregoing is true and correct. Igned Patsy Clugston Title Sr. Title Sr. This space for Federal or State Office use)	I w/1016 bbls 60 Quality Slickwater foam CIFP. Trouble. RD WL. RD frac valve. 5 Kill well w/40 bbls. TOOH. PU & lled liner top from 3360' to 3361'. Blew and hole & ND BOP, NU frac valve & 56,' 61', 64', 70', 86', 898', 5100', 06', es. RD WL. 5/11/05 Acidized w/10 bbls Displaced w/48 bbls fluid & 81,600 scf N2. 7500' & C/O to 7788'. TOOH w/mill. RIH neck. RD & released rig @ 1700 hrs 5/19/05.