

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires: July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other Instructions on the reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Devon Energy Production Co. L.P. Attn: Kenny Rhoades

3a. Address

1751 Highway 511 Navajo Dam, NM 87419

3b. Phone No. (include area code)

(505)320-6310

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1240' FNL & 1175' FEL

/4,

/4,

Sec. 3

, T 30N

R. 7W

Latitude

Longitude

5. Lease Serial No.

SF-079001

6. If Indian, Allottee, or Tribe Name

7. If Unit or CA. Agreement Designation

Northeast Blanco Unit

8. Well Name and No.

NEBU 485

9. API Well No.

30-039-27324

10. Field and Pool, or Exploratory Area

Basin Fruitland coal

11. County or Parish, State

Rio Arriba

NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Altering Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and abandon

☐ Plug back

☐ Production (Start/ Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-off

☐ Well Integrity

☒ Other **CBM Re-Cavitation**

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required susequnet reports shqll be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in anew interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Devon Energy proposes to clean out and remove 5-1/2" liner. Pressure test 7" casing to 500 psi. Underream open hole. Re-cavitate openhole and remove near wellbore coal material. Pending well bore condition, may re-install 5-1/2" liner or produce openhole. Using 24 hr rig package work should take appx. 21 days

CONDITIONS OF APPROVAL
Adhere to previously issued stipulations.

RECEIVED
2003 MAY 23 AM 10:45
070 Farmington, NM

14. I hereby certify that the foregoing is true and correct.
Name (Printed/ Typed)

Kenny Rhoades

Signature

Ky Rhoades

Title

Company Representative

Date

5-18-03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/s/ Jim Lovato

Title

Date

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

MAY 28 2003

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOC

Conditions of Approval: Notice of Intent to Recavitate

Devon Energy Production Company
NEBU No. 485
1240' FNL & 1175' FEL
Sec 3-30N-7W

- 1) No construction, drilling or workover activities can be conducted between November 1 and March 31 due to Bald Eagle Wintering. All recavitation activities must be confined to the original disturbed area. Refer and adhere to the original permit requirements and the following:
 - a) All workover pits will be fenced during the recavitation operation and fenced closed after the completion of the work.
 - b) Pits must be lined with 12 mil, or greater, reinforced liner.
 - c) All coal fines must be confined to the pit. Any off location spray of coal fines must be immediately washed down with fresh water.
 - d) Pits must be reclaimed within 90 days of the completion of the workover operations.
- 2) Notify the Farmington Filed Office Inspection and Enforcement Division @ (505) 599-8907 within 24 hours prior to commencing well bore recavitation operations.
- 3) Prior to commencing recompletion operations, BOPE must be installed and tested in accordance with the requirements outlined in Onshore Order No. 2.
- 4) Within 30 days of completion of the operations as proposed, file one original and three copies of Sundry Notice (form 3160-5) detailing the work conducted.