This form is not to be used for reporting packer leakage tests in Southeast New Mexico

Oil Conservation Division

Northwest New Mexico Packer-Leakage Test

Page 1 Revised June 10, 2003

Operator COF	5		Lease	Name SAN	JUAN 28-7	UNIT		Well No. 96
ocation of We	ell: Unit L	etter G Se	ec 08	Twp 027N	Rge	007W	API	# 30-039-07129
	Na	ame of Reservoir or Pool		Type of Prod		Method of Prod		Prod Medium
Upper Completion	PC	To the last	Gas		FI	ow		Tubing
Lower Completion	MV	Alexander	Gas	MILE.	FI	ow		Tubing
			Pre-Flow S	Shut-In Pressu	ire Data	5		
Upper Completion		te, Shut-In 8/2015		of Time Shut-In	SI	Press. PSIG	209	Stabilized?(Yes or No) Yes
Lower Completion	A STATE OF THE STA	te, Shut-In 8/2015	Length of Time Shut-In 96 hours		SI	Press. PSIG	. PSIG 341	Stabilized?(Yes or No) Yes
Commenced Time		6/22/2015 Lapsed Time	PRES	Zone Pro	oducing (Up	oper or Low ne	er): LC	
(date/tim		Since*	Upper zone	Lower zone	Temperat		3	Remarks
6/23/2015 6:52	::39 AM	30	209	194				
6/24/2015 8:45	:44 AM	56	209	104		Returne	ed the pc	to production
oduction rat	e during to	est						
il:	BPOD	Based on:	Bbls. In	Hrs.		Grav.	<u> 34</u>	GOR
as		MCFPD; Test th	ru (Orifice or M	leter)	7 7 7 7 7			
			Mid Toot S	hut-In Pressu	ro Data			
Upper Completion	Hour, Da	te, Shut-In		of Time Shut-In	THE COURSE OF THE PARTY OF THE	Press. PSIG		Stabilized?(Yes or No)
Lower Completion	Hour, Da	te, Shut-In	Length	of Time Shut-In	SI	Press. PSIG		Stabilized?(Yes or No)

(Continue on reverse side)

OIL CONS. DIV DIST. 3

JUL 07 2015

Flow Test No. 2

Zone Producing (Upper or Lower)

Time	Lapsed Time Since*	PRESSURE		Prod Zone	
(date/time)		Upper zone	Lower zone	Temperature	Remarks
				3477	
	Lui Te				
				1	
	Lat. 14; M. L.		E18 15 18		" I have been a second
Contract Contract	C3-148 1-11				
					A CONTRACTOR OF THE PARTY OF
roduction rate during	g test D Based on:	Bbls. In	Hrs.		Grav. GOR
il:BPO	D Based on:	Bbls. In	The Francisco		GravGOR
il: BPO	D Based on:	17 (6.8)	The Francisco		GravGOR
il:BPO	D Based on:	17 (6.8)	The Francisco		GravGOR
il: BPO	D Based on:	17 (6.8)	The Francisco		GravGOR
il: BPO	D Based on:	17 (6.8)	The Francisco		GravGOR
emarks:	D Based on:MCFPD; Test th	hru (Orifice or M	eter)		
emarks:	D Based on:	hru (Orifice or M	eter)		
emarks:	D Based on: MCFPD; Test the information herein of	hru (Orifice or M	eter)		
emarks: hereby certify that the pproved:	D Based on: MCFPD; Test the information herein of	hru (Orifice or M	eter)	to the best of	
emarks: hereby certify that the pproved:	D Based on: MCFPD; Test the information herein of the second sec	hru (Orifice or M	and complete	to the best of	my knowledge.

NORTHWEST NEWMEXICO PACKER LEAKAGE TEST INSTRUCTIONS

A packer leakage test shall be commenced on each multiply completed well within seven days after actual
completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion.
Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or
chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or
the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when
requested by the Division.

Commenced at:

- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to lack of a pipeline connection the flow period shall be three hours.

- Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure
 for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall
 remain shut-in while the zone which was previously shut-in is produced.
- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).

Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.