Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

AUTHORIZATION REQUIRED FOR OPERATIONS

ON FEDERAL AND INDIAN LANDS

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

Lease Serial No. NMSF078828

892000844E

CONDITIONS OF APPROVAL

0.	EASTERN NAVAJO
7.	If Unit or CA/Agreement, Name and/or No.

Type of Well     Oil Well		Well Name and No.     GALLEGOS CANYON UNIT 354				
Name of Operator     BP AMERICA PRODUCTION	9. API Well No. 30-045-26471	9. API Well No. 30-045-26471-00-S1				
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401		3b. Phone No. (include area code Ph: 281-366-7148	10. Field and Pool, UNKNOWN	10. Field and Pool, or Exploratory UNKNOWN		
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description		11. County or Parisi	h, and State		
Sec 29 T28N R12W NESE 14 36.629900 N Lat, 108.128360			SAN JUAN CO	JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off		
Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	■ New Construction	Recomplete	Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon			
61	☐ Convert to Injection	□ Plug Back	☐ Water Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved	ally or recomplete horizontally, it will be performed or provide operations. If the operation re- pandonment Notices shall be file inal inspection.)	give subsurface locations and measurements the Bond No. on file with BLM/BI/sults in a multiple completion or reced only after all requirements, included	g date of any proposed work and apprinted and true vertical depths of all period. Required subsequent reports shall lompletion in a new interval, a Form 3 ling reclamation, have been completed.	tinent markers and zones. be filed within 30 days 160-4 shall be filed once		
Please see the attached procedure and the BLM requested reclamation plan documents.  NOV 16 30						
In accordance with NMOCD P	it Rule 19.15.17.9 NMAC		stem during	2015		
BLM'S APPROVAL OR ACC ACTION DOES NOT RELIE OPERATOR FROM OBTAIN	VE THE LESSEE AND	Notify NMOCD 24 hr. prior to beginning operations				

14. I hereby certify that the	ne foregoing is true and correct.  Electronic Submission #318642 verifie For BP AMERICA PRODUCTIO Committed to AFMSS for processing by JA	N CO.	sent to the Farmington	
Name (Printed/Typed)	TOYA COLVIN	Title	REGULATORY ANALYST	Page 1
Signature	(Electronic Submission)	Date	10/05/2015	Harry To
	THIS SPACE FOR FEDERA	AL OR	STATE OFFICE USE	
Approved By JACK SAVAGE			ETROLEUM ENGINEER	Date 11/12/2015
certify that the applicant hol	ry, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease licant to conduct operations thereon.	Office	Farmington	
	1 and Title 43 U.S.C. Section 1212, make it a crime for any per or fraudulent statements or representations as to any matter w			r agency of the United

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*





September 14, 2015

**NMOCD** 

BP would like to permanently abandon the **Gallegos Canyon Unit # 354** well, as per the proposed procedure and wellbore sketches.

West Kutz Pictured Cliffs
1450' FSL and 890' FEL, Section 29, T28N, R12W
San Juan County, New Mexico / API 30-045-26471
Lat: / Lat:

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
  regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
  location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
  Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND
  wellhead and NU BOP. Function test BOP.
- 3. Rods: Yes\_\_\_\_, No\_\_X\_\_, Unknown\_\_\_\_.
  Tubing: Yes\_\_X\_\_, No\_\_\_\_, Unknown\_\_\_\_\_, Size\_\_\_\_\_2.375"\_\_, Length \_\_\_\_\_\_1369'
  Packer: Yes\_\_\_\_\_, No\_\_X\_\_, Unknown\_\_\_\_\_, Type\_\_\_\_\_\_.
  If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
- 4. Plug #1 (Pictured Cliffs interval and Fruitland top, 1248' 849'): Round trip gauge ring or mill to 1248', or as deep as possible. PU and TIH with 4.5" cement retainer, set at 1248'. Pressure test tubing to 1000 PSI. Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plug as appropriate. Mix and pump 35 sxs Class B cement above CR to isolate the Pictured Cliffs interval and cover the Fruitland top. PUH.
- 4. Plug #2 (Kirtland top and Surface Casing shoe, 189' to Surface): Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 20 sxs Class B cement and spot a balanced plug inside the casing from 189' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the 4.5" casing and the BH annulus to surface. Shut well in and WOC.

ND BOP and cut off wellhead below surface casing flange. Fill annuli with cement as necessary.
 Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower
 report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per
 BLM stipulations.

## Gallegos Canyon Unit #354

#### Current

West Kutz Pictured Cliffs

1450' FSL, 890' FEL, Section 29, T-28-N, R-12-W, San Juan County, NM / API #30-045-26471

Lat \_\_\_\_\_ / Long \_\_\_\_\_

Today's Date: 8/31/15 TOC @ Surface, circulated per sundry Spud: 7/12/15 Completed: 8/25/85 12-1/4" hole 8-5/8" 24#, K-55 Casing set @ 129' Cement with 50 sxs (Circulated to Surface) Elevation: 5624' GL 5632 KB Kirtland @ 139' 42 jts 2.375" tubing at 1369' KB Fruitland @ 889' Pictured Cliffs @ 1292' Pictured Cliffs Perforations: 1298' - 1338' 4.5",10.5#, K-55 Casing set @ 1439' Cement with 225 sxs (278 cf) Circulate cement to surface

TD 1440' **PBTD 1420'** 

6.25" hole

# Gallegos Canyon Unit #354

### Proposed P&A

West Kutz Pictured Cliffs

1450' FSL, 890' FEL, Section 29, T-28-N, R-12-W, San Juan County, NM / API #30-045-26471

Today's Date: 8/31/15

Spud: 7/12/15 Completed: 8/25/85

Elevation: 5624' GL

5632 KB

12-1/4" hole

Kirtland @ 139'

Fruitland @ 889'

Pictured Cliffs @ 1292'

6.25" hole

Lat \_\_\_\_\_/Long \_\_\_\_

TOC @ Surface, circulated per sundry

8-5/8" 24#, K-55 Casing set @ 129' Cement with 50 sxs (Circulated to Surface)

> Plug #2: 189' - 0' Class B cement, 20 sxs

Plug #1: 1248 ' - 849' Class B cement, 35 sxs

Set CR @ 1248'

Pictured Cliffs Perforations: 1298' – 1338'

4.5",10.5#, K-55 Casing set @ 1439' Cement with 225 sxs (278 cf) Circulate cement to surface

TD 1440' PBTD 1420'

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Gallegos Canyon Unit #354

#### **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.