

RECEIVED

APR 11 2017

Form 3160-5

(March 2012)

Farmington Field Office
Bureau of Land Management

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well.
Use Form 3160-3 (APD) for such proposals

FORM APPROVED

Budget Bureau No. 1004-0137

Expires March 31, 2014

5. Lease Serial No.

NMNM-99735

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Synergy 21-7-5 # 133

9. API Well No.

30-043-21038

10. Field and Pool, or Exploratory

Basin Fruitland Coal

11. County or Parish, State

Sandoval County, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

Oil Well Gas Well Other

2. Name of Operator

Synergy Operating, LLC (OGRID # 163458)

3a. Address

PO Box 5513
Farmington, NM 87499

3b. Phone No. (include area code)

(505) 325-5549

4. Location of Well (Footage, Sec, T. R., M, or Survey Description)

Unit L, 1470' FSL, 1125' FWL, Sec 05, T21N - R07W

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

Notice of Intent
 Subsequent Report
 Final Abandonment Notice

Acidize
 Alter Casing
 Casing Repair
 Change Plans
 Convert to Injection
 Deepen

Fracture Treat
 New Construction
 Plug & Abandon
 Plug Back
 Production (Start/Resume)
 Reclamation

Recomplete
 Temporary Abandon
 Water Disposal
 Water Shut-Off
 Well Integrity
Other: _____

13. Describe Proposed or Completed Operations: (Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with the BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

02-24-2017 - MIRU BASIN PERFORATING. SICP = 4#, BLOW DOWN CASING. RIH AND SET 5-1/2" CIBP @ 660'. POOH. RDMO. EXISTING FRUITLAND COAL PERFORATIONS BELOW CIBP FROM 677' TO 697'

03-15-2017 - RU B&B WATER TRUCK, LOAD HOLE SLOWLY FROM SURFACE WITH 7.3 BBLS TEST CASING 50#. RD.

DUE TO ADVERSE SPRING ROAD CONDITIONS, REQUEST ADDITIONAL THIRTY (30) DAYS TO SCHEDULE WITNESSED MIT CASING TEST TO 550#.

PERFORM WITNESSED PRESSURE TEST AND SUMBIT CHART WITH SUBSEQUENT SUNDRY NOTICE.

MIT WORK WILL BE PERFORMED BY MAY 15, 2017.

APR 11 2017
FARMINGTON FIELD OFFICE
BY: William Tambekou

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

THOMAS E. MULLINS tom.mullins@synergyoperating.com

Title ENGINEERING MANAGER

Signature

Date NOVEMBER 28, 2016

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

OIL CONS. DIV DIST. 3

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

APR 14 2017

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD