

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Vacant, Division Director
Oil Conservation Division



January 11, 2018

BP America Production Co.
Toya Colvin
737 North Eldridge Parkway
Houston, TX 77079

Re: Bradenhead Test Failure
Well: Neil A #7A, UL D Sec 33 Twn 32N Rge 11W, API # 30-045-22463

Dear Ms. Colvin:

The 2017 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **March 5, 2018**. Initial Surface Casing psi was 113. Initial Production Casing psi was 118. Production casing did not drop. However, the gas analysis indicates same gas on surface casing and production casing

Reference: **RBDMS MPK1722231679** on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File