

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Serial No. JIC240
2. Name of Operator BILLCO ENERGY	6. If Indian, Allottee or Tribe Name JICARILLA APACHE
3a. Address #28 COUNTRY ROAD 1490 LAPLATA, NM 87418	7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) Ph: 303.278.6757 Ex: 303.278.6757	8. Well Name and No. JICARILLA 4-26-2 Boulder #2
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 26 T28N R1W NWNE	9. API Well No. 30-039-07247-00-S1
	10. Field and Pool, or Exploratory BOULDER
	11. County or Parish, and State RIO ARRIBA COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize <input type="checkbox"/> Deepen <input type="checkbox"/> Production (Start/Resume) <input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing <input type="checkbox"/> Fracture Treat <input type="checkbox"/> Reclamation <input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair <input type="checkbox"/> New Construction <input type="checkbox"/> Recomplete <input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans <input checked="" type="checkbox"/> Plug and Abandon <input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Convert to Injection <input type="checkbox"/> Plug Back <input type="checkbox"/> Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

#2, sec 26, T28N, R1W, API# 3003907247

1. Pull tubing
2. Set cement retainer @ 3425
3. Cement with 52 sxs. cement. Leave 10 sxs. on top of retainer.
4. Perforate with 2 spf 2766 and 146
5. Set cement retainer @ 2716
6. Squeeze cement with 13 sxs. cement.
7. Circulate 111 sxs. cement from 136 to surface. Returns to surface from annulus.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #22572 verified by the BLM Well Information System For BILLCO ENERGY, sent to the Rio Puerco Committed to AFMSS for processing by Angie Medina-Jones on 05/30/2003 (03AMJ0461SE)	
Name (Printed/Typed) ROGER KNIGHT	Title AUTHORIZED REPRESENTATIVE
Signature (Electronic Submission)	Date 05/30/2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By BRIAN W DAVIS	Title DIVISION OF MULTI-RESOURCES	Date 05/30/2003
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office Rio Puerco		



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Lease Jicarilla
Well # 2

sec 26 T 28N R1W

contract # 241



Cement- 111 sxs cement

Perf @ 146 ft

CR @ 2716 5.5"

perf @ 2766 ft

100 ft fill

Cement- 13 sxs

10 sxs on top of cement retainer

CR @ 3425 5.5"

Cement- 42 sxs cement

PROD CMT 52 SXS CMT

TOTAL CMT 165 SXS CMT

IN REPLY REFER TO
3162.3-1 (017)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
Albuquerque Field Office
435 Montano N.E.
Albuquerque, New Mexico 87107

Company Billico Energy

Well No. Boulder No. 2

Location 660' FSL & 2310' FEL Sec. 26, T28N, R1W, NMPM

Lease No. Jicarilla Contract 240

Government Contacts:

Bureau of Land Management , Albuquerque Field Office Office 505.761.8700
Manager: Steve Anderson, Assistant Field Manager 505.761.8982
Petroleum Engineer: Brian W. Davis Office 505.761.8756, Home 505.323-8698,
Pager 505.969.0146, Cell 505.249.7922,
Petroleum Engineering Technician: **Bryce Hammon, Office 505.759.1823, x-31, Cell 505.320.9741**
BLM Geology / Environmental Contact: Richard Wilson, 505.761.8756 Office

GENERAL REQUIREMENTS
FOR
OIL AND GAS OPERATIONS FEDERAL & INDIAN LEASES

1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
2. For wells on Indian leases, Bryce Hammond with the Jicarilla Nation Tribal Oil and Gas Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-1823, x-31 office, (505) 320-9741 cell. Office hours are 7:45 a.m. to 4:30 p.m.
3. Blowout prevention equipment is required.
4. The sundry is approved with the following change:
Plug 1 – CR @ 3425, 42 sacks below, 10 sxs above – okay

Plug 2 – CR @ 2716, Perforations at 2766, 165 sxs below, 65 sxs above – need to cover Cliff House Formation

Plug 3 – Perforate at 186, 82 sxs to surface inside and out.