



## **Conditions of Approval: Notice of Intent to Recavitate**

Devon Energy Production Company  
NEBU No. 454  
1010' FNL & 1310' FEL  
Sec 33-31N-7W

- 1) Refer and adhere to the original permit requirements and the following:
  - a) All workover pits will be fenced during the recavitation operation and fenced closed after the completion of the work.
  - b) Pits must be lined with 12 mil, or greater, reinforced liner.
  - c) All coal fines must be confined to the pit. Any off location spray of coal fines must be immediately washed down with fresh water.
  - d) Pits must be reclaimed within 90 days of the completion of the workover operations.
- 2) Notify the Farmington Filed Office Inspection and Enforcement Division @ (505) 599-8907 within 24 hours prior to commencing well bore recavitation operations.
- 3) Prior to commencing recompletion operations, BOPE must be installed and tested in accordance with the requirements outlined in Onshore Order No. 2.
- 4) Within 30 days of completion of the operations as proposed, file one original and three copies of Sundry Notice (form 3160-5) detailing the work conducted.