



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Lori Wrotenberg**

Director

**Oil Conservation Division**

June 23, 2003

Mr. Sterg Katirgis  
Williams Production Company  
PO Box 3102  
Tulsa OK 74101

Re: Rosa Unit 149B, J-12-31N-06W API 30-039-26599

Dear Mr. Katirgis:

The 2003 Packer Leakage Test on the referenced well does not provide sufficient data. In order to comply with Rule #112A, you are hereby directed to retest the well to show separation of the zones. In the event cross-over of pressure is not obtained on flow test #1 continue with flow test #2'. Conduct this test prior to August 15, 2003. Review the Rules for proper filing procedures. Notify the Aztec OCD in time to witness the retest.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T. Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: CTP  
Well File