

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor
Joanna Prukop
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

June 25, 2003

Gary Brink
Energen Resources
2198 Blmfld Hwy
Farmington NM 87410

RE: Canedlario ET AL # 1, J 01-27N-09W API 30-045-06809

Dear Mr. Brink:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before September 15, 2003.

Reference RBDMS CTP0317562115 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin

Deputy Oil & Gas Inspector

Charlie T. L. rrin

cperrin@state.nm.us

CTP/mk

CC: CTP

Well File