



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenberg

Director

Oil Conservation Division

July 16, 2003

Don L. Hanosh
ENERDYNE, LLC
PO Box 502
Albuquerque NM 87103

Re: Western Federal #1, I-01-30N-16W, API 30-045-26321

Dear Don:

The Bradenhead test report submitted on the above well indicates no bradenhead valve present. Review Rule 115.B.

No pressures were reported on the test.

You are hereby directed to retest the well. Submit the re-test report and a well configuration including the wellhead and casing strings schematic before August 15, 2003.

Reference RBDMS CTP0319647716 on future correspondence.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File