



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

June 22, 2006

Certified Mail

Return Receipt #: 7006 0810 0000 5448 5121

Janet Ray
B P America
200 Energy Court
Farmington NM 87401

Re: Warren Com #2, G-14-28N-09W, API # 30-045-20063

Dear Ms. Ray:

The 2006 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before September 24, 2006. Intermediate psi of 700 was reported dated May 8, 2006.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top; provide gas analysis from both the production and intermediate casing.

Reference RBDMS EHV0617249100 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 17.

Sincerely yours,

Henry Villanueva
Oil & Gas Inspector
District III
enriques.villanueva@state.nm.us

CC: Well File