Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 200

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS 12 OC		Expires: March 51, 2007
		5. Lease Serial No.
		NMSF 079160 (77 28 29 77 75)
Do not use this form for proposals		6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160 - 3	3 (APD) for such proposals.	The second secon
	RECEIVED	ALCOMB ON
SUBMIT IN TRIPLICATE- Other instruction்s) on reverse (side: 🔠		7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other		Rincon Unit
		8. Well Name and No.
2. Name of Operator Chevron Midcontinent, L.P. (241333)		Rincon Unit # 231R
Ba. Address	3b. Phone No. (include area code)	30-039-26691
15 Smith Road Midland, Texas 79705	432-687-7158	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description	on)	Basin Dakota/Blanco-Mesaverde
1943' FSL & 1595' FWL, UL K, Sec. 12, T26N, R07W		11. County or Parish, State
2, 10 100 00 10,00 1,000 12, 1001, 1001		Rio Arriba, New Mexico
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Acidize	Deepen Production (S	Start/Resume) Water Shut-Off
✓ Notice of Intent	Fracture Treat Reclamation	Well Integrity
	New Construction Recomplete	Other Upgrade Plunger
Subsequent Report Casing Repair	Plug and Abandon Temporarily A	Abandon Lift Controller
Final Abandonment Notice Convert to Injection	Plug Back Water Disposa	
Attach the Bond under which the work will be performed or p following completion of the involved operations. If the operatesting has been completed. Final Abandonment Notices mudetermined that the site is ready for final inspection.) Chevron Midcontinent, L.P. proposes to replace the new modern controller will react to line pressures remonitoring and trouble shooting along with develop from this plunger lift controller upgrade.	ation results in a multiple completion or recompletion ast be filed only after all requirements, including reclar e outdated, damaged and less efficient plunger esulting in increased run times and uplift of p	n in a new interval, a Form 3160-4 must be filed once amation, have been completed, and the operator has r lift controller on this Rincon Unit well. This production in this well. Remote electronic
14. I hereby certify that the foregoing is true and correct		
Name (Printed/Typed)	Title P	
Alan W. Bohling	Title Regulatory Agent	
Signature Clance Grhling	Date	08/14/2006 ACCEPTED FOR RECOF
THIS SPACE FO	OR FEDERAL OR STATE OFFIC	EUSE

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Date Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.

AUG 2 5 2006

(Instructions on page 2)

