

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APP) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BP America Production Co

3a. Address

200 Energy Ct. Farmington, NM 87402

3b. Phone No. (include area code)

505-326-9221

4. Location of Well (Boothage, Sec., T., R., M., or Survey Description)

NW/SE Sec 27 T28N R8W

5. Lease Serial No.

NMSP 078566

6. If Indian, Allottee or Tribe Name

1:15

7. If Unit or CA/Agreement, Name and/or No.

NM

8. Well Name and No.

Story LSIA Story LS8

9. API Well No.

29248 30045210
3004529528 (INV) (PC)

10. Field and Pool, or Exploratory Area

Picacho Cliffs/Mesaverde

11. County or Parish, State

San Juan, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other Allocation methodology

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP Has Completed a Duface Commingled production well test for asor ~~PC~~ PC-911. Accordingly, the following daily allocation will be used to allocate monthly production for BLM Ltr. 3162.3-2 (07327) formation Gas Oil BBLs Water BBLs
mesaverde 65mcp 49.62% 0 1
Picacho Cliffs Celemer 60.38% 0 1
131mcp 0 BBLs 2 BBLs

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Rhonda Compher

Title

Business Analyst

Signature

Rhonda Compher

Date

12 May 2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

AUG 05 2003

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE