

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or re-enter to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE RECEIVED

070 FARMINGTON NM

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325 - 1821

Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FSL & 1850' FWL
Sec. 17, T25N, R7W, NMPM

5. Lease Designation and Serial No.

SF 078477

6. If Indian, Allotted or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Nordhaus #4

9. API Well No.

30 039 20139

10. Field and Pool, or Exploratory Area

Ballard Pictured Cliffs

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plan to plug well as follows:


Set cast iron bridge plug at approximately 2130'. This is 50' above Pictured Cliffs top at 2179'.

Spot cement on top of cast iron bridge plug to cover Fruitland top at 2042'.

Spot cement plug to cover Ojo Alamo top at 1449'. (1708' - 1399')

Perforate 50' below surface casing (91'). (141' - surface)

Pump cement down casing and circulate to surface.



14. I hereby certify that the foregoing is true and correct

Signed

John Alexander
John Alexander

Vice-President

Date

7/20/2006

(This space for Federal or State office use)

Original Signed: Stephen Mason

Approved by

Title

Date

JUL 31 2006

Conditions of approval, if any: