CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office

OH CONSEDVATION DIVIS

DISTRICT I	OIL CONSERVATION DIVISION					
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088			WELL API NO.		
DISTRICT II	Santa Fe, New M	exico 8750	4-2088	30-045-28993		
P.O. Drawer DD, Artesia, NM 88210				5. Indicate Type of Lease		
DISTRICT III			a a a a a a a a a a a a a a a a a a a	STATE	FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410)		SEP 2006	6. State Oil & Gas Lease No.		
	Y NOTICES AND REPORTS ON		TE ONL			
	R PROPOSALS TO DRILL OR TO DEEPI		ACK TO A	7. Lease Name or Unit Agreen	ent Name	
DIFFEREN	T RESERVOIR. USE "APPLICATION FO			Manalan		
1. Type of Well	(FORM C-101) FOR SUCH PROPOSA	LS.)	- VSE 22 12 W 3	Moseley		
MEIT OIL	GAS WELL X C	THER:				
2. Name of Operator ROBERT L. B.	AYLESS, PRODUCER LLC			8. Well No.		
3. Address of Operator				9. Pool name or Wildcat		
P.O. BOX 168,	FARMINGTON, NM 87499			Flora Vista Fruit	land	
4. Well Location Unit Letter K	; 1470 Feet from the	South	Line and 164	5 Feet from The	West Line	
Section 2	Township 30N	Range	12W	NMPM SAN JUA	N County	
Section 2	10. Elevation		nether DF, RKB, RT, GR, etc		1 County	
5788 GR						
	eck Appropriate Box to Ind	icate Natu	-			
NOTICE OF	INTENTION TO:	 1	SUBS	EQUENT_REPORT		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	Ц	REMEDIAL WORK	ALTERING	CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OP	NS. PLUG AND	ABANDONMENT	
PULL OR ALTER CASING			CASING TEST AND CEME	NT JOB		
OTHER:			OTHER: Produce Fru	itland Sand only	x	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed						
work) SEE RULE 1103.						
8/30/2006: Rig up JC Well Service workover rig. Blow well down. Trip out and lay down rods.						
Nipple up BOP. Tripped out and tallied tubing. Rig up Blue Jet and trip in with Weatherford						
5 ½" composite drillable bridge plug. Set bridge plug at 1950' KB. Rig down Blue Jet. Well blowing lightly. Trip in with 2 3/8" tubing. Nipple down BOP and rig up wellhead. Rig up to swab.						
blowing ngmiy. Trip in with 2 3/6 thoung, rappie down BOF and rig up wemiead. Kig up to swap.						
	A					
I hearby certify that the information al	ove is true and complete to the st of my know	vledge and belief.				
SIGNATURE ON	~ W/ / ///	TITLE	ENGINEER	DATE	9/1/2006	
	- MANI					
TYPE OR PRINT NAME	Tom McCarthy			TELEPHONE NO.	(505) 326-2659	
(This space for State Use) //	Villanueva		deputy on 8 gas insp	PETTOR DIST AU	SEP 0 5 2001	
APPROVED BY	Manueva	TITLE	BELLIA AIT & DAY INSI	DATE	SEP 0 5 2008	

8