

38. GEOLOGIC MARKERS

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP		TRUE VERTICAL DEPTH
					NAME	MEASURED DEPTH	
					KIRTLAND	1337'	
					PICTURED CLIFFS	3266'	
					CLIFFHOUSE	5049'	
					MENEFEE	5212'	
					POINT LOOKOUT	5611'	
					MANCOS	6149'	
					DAKOTA	7780'	

000000