

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

SF - 81098

6. If Indian Allottee or tribe Name

2007 JAN 26 AM 10:00

7. Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

8. Well Name and No.

ELLIOTT GAS COM X IE

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

BP AMERICA PRODUCTION COMPANY

9. API Well No.

30-045-33020

3a. Address

PO BOX 3092 HOUSTON, TX 77253

3b. Phone No. (include area code)

281-366-3866

10. Field and Pool, or Exploratory Area

BLANCO MESAVERDE

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1535' FNL & 1090' FEL; SEC 09 T30N R09W SENE

11. County or Parish, State

SAN JUAN, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☒ Other

Subsequent Completion RPT

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

12/19/2006 MIRU PRESS TEST BOP 2500# HIGH 250# LOW CHARTED O.K.

12/20/2006 CBP SET @ 5600'.

01/03/2007 PERSSURE TESTED THE 4 1/2 " 11.6 # P-110 CASING TO 7,300 PSI IT HELD OK 15 MIN.

01/04/2007 PERFORATED THE MESA VERDE FROM 5,275' TO 5,418'.

01/05/2007 PUMPED DOWN 4.5 " 11.6 # P-110 CASING. @ 60 BBLs. / MIN. USING 150,000 LBS. OF 16/30 BRADY SAND. IN SCHLUMBERGER CLEAR FRAC. AND 70 % QUALITY FOAM AND N2. JUST WENT TO OUR FLUSH WHEN WE PRESSURED TO OUR TREATING PRESSURE MAX. SHUT DOWN.

01/09/2007 TEST BOP 2500# HIGH 250# LOW CHARTED O.K.

01/18/2007 DRILL OUT CBP @ 5600'

01/22/2007 LAND 2 3/8" TUBING @ 7611' RD MOL.

14. I hereby certify that the foregoing is true and correct

Name (Printed/typed)

Kristina Hurts

Title Regulatory Analyst

Signature

Date 01/25/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

FARMINGTON FIELD OFFICE

NMOCD 8 1/31/07