

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
**SUNDRY NOTICES AND REPORTS ON WELLS**

**Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

FORM APPROVED  
OMB No. 1004-0135  
Expires July 31, 1996

5. Lease Serial No.  
**SF 080436-B**

6. If Indian, Allottee or Tribe Name

**207 FEB 28/AM 10: 58**

7. If Unit or CA/Agreement, Name and/or No.

**Canada Ojitos Unit  
210 FARMINGTON NM**

8. Well Name and No.

**#43 (H-8)**

9. API Well No.

**30-039-24505**

10. Field and Pool, or Exploratory Area

**West Puerto Chiquito Mancos**

11. County or Parish, State

**Rio Arriba, New Mexico**

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

**Benson-Montin-Greer Drilling Corp.**

3a. Address

**4900 College Blvd., Farmington, NM 87402**

3b. Phone No. (include area code)

**505-325-8874**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**Sec. 8-T26N-R01W**

**1632 FNL & 1139 FEL**

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

**RCVD MAR2'07**

TYPE OF SUBMISSION	TYPE OF ACTION				OIL CONS. DIV.
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Shut-Off	
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity	
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other	
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon		
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal		

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Benson-Montin-Greer Drilling proposes to isolate the Sanostee Zone and swab test. If non-productive - set CIBP covered with sand. Run 2-3/8" tubing to approximately 7500'. Put on pumping unit. If Sanostee proves productive - run 2-3/8" tubing to approximately 7820'. Put on pumping unit.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

**Trudy Grubelnik**

Title

**Production Clerk**

Signature

Date

**February 26, 2007**

**THIS SPACE FOR FEDERAL OR STATE USE**

Approved by

**Original Signed: Stephen Mason**

Title

Date

**FEB 26 2007**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

**NMOCD**