## **UNITEDSTATES** DEPARTMENT OF THE INTERIOR

## **BUREAU OF LAND MANAGEMENT**

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

Do not use this form for proposals to drill or to re-enter an

FORMAPPROVED	
OM B No. 1004-0137	
Expires: March 31, 2	2007

5. Lease Serial No.	
NMSF078497	

_				
6.	If Indian.	Allottee	or Tribe	Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.  1. Type of Well	7. If Unit or CA/Agreement, Name and/or No.	
2. NameofOperator ConocoPhillips Company 3a. Address PO BOX 4289 Farmington NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	→	
2. NameofOperator ConocoPhillips Company 3a. Address PO BOX 4289 Farmington NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		
ConocoPhillips Company  3a. Address  3b. PhoneNo.(include area code)  PO BOX 4289 Farmington NM 87499  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	8. Well Name and No.	
a. Address  PO BOX 4289 Farmington NM 87499  Control of Well (Footage, Sec., T., R., M., or Survey Description)  3b. PhoneNo.(include area code) (505)326-9597  Control of Well (Footage, Sec., T., R., M., or Survey Description)	SAN JUAN 28-7 UNIT 232G  9. API Well No.	
PO BOX 4289 Farmington NM 87499 (505)326-9597  Location of Well (Footage, Sec., T., R., M., or Survey Description)	30-039-29950	
• • • •	10. Field and Pool, or Exploratory Area	
	Blanco Mesaverde/ Basin Dakota	
1900 SOUTH 1900 EAST JL: J, Sec: 20, T: 28N, R: 7W	11. County or Parish, State RIO ARRIBA NM	
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPEOF SUBMISSION TYPEOF ACTION		
Acidize Deepen Production (S	Start/Resume)	
Notice of Intent Alter Casing Fracture Treat Reclamation	Well Integrity	
X Subsequent Report Casing Repair New Construction Recomplete	X Other Completion	
Change Plans Plugand Abandon Temporarily A	Abandon <u>Detail</u>	
Final Abandonment Notice Convert to Injection Plug Back Water Dispos	al	
01/22/07 MIRU Key Rig 11. NU BOP. 01/23/07 RIH w/170 jnts 2 3/8" tbg and ta cmt from 7216' to 7268' (PBTD). Circ clean. RD swivel. POOH w/170 jnts tbg. f POOH. Run GR/CCL log strip from 7278' to 6780'. POOH. LD tools.	ag fill @ 7216'. RU power swivel. Drill RU W/L. RIH w/guage ring to 7278'.	
	OIL CONS. DIV.	
	DIST. 3	
14. I hereby certify that the foregoing is true and correct	DIST. 3	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Juanita Farrell  Title Regulatory Sp		
Name (Printed/Typed)		
Name (Printed/Typed)  Juanita Farrell  Title Regulatory Sp	pecialist	
Name (Printed/Typed)  Juanita Farrell  Signature  Title Regulatory Sp.  Date 03/12/2007  THIS SPACE FOR FEDERAL OR STATE OFFICE	Decialist  E USE	
Name (Printed/Typed) Juanita Farrell  Signature  Title Regulatory Sp.  Date 03/12/2007  THIS SPACE FOR FEDERAL OR STATE OFFICE  Approved by  Title	pecialist	
Name (Printed/Typed)  Juanita Farrell  Signature  Title Regulatory Sp.  Date 03/12/2007  THIS SPACE FOR FEDERAL OR STATE OFFICE	Decialist  E USE	

(Instructions on page 2)