

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0157  
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. <b>NMSF-079596</b>
2. Name of Operator <b>XTO Energy Inc.</b>		6. If Indian, Allottee or Tribe Name <b>2007 MAR 23 AM 10:50</b>
3a. Address <b>2700 Farmington Ave., Bldg. K. Ste 1 Farmington,</b>	3b. Phone No. (include area code) <b>505-324-1090</b>	7. If Unit or CA/Agreement, Name and/or No. <b>RECEIVED</b>
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <b>990' FNL &amp; 790' FWL SEC 15D-T27N-R10W</b>		8. Well Name and No. <b>CM MORRIS B #1</b>
		9. API Well No. <b>30-045-06561</b>
		10. Field and Pool, or Exploratory Area <b>FULCHER KUTZ PICTURED CLIFFS</b>
		11. County or Parish, State <b>SAN JUAN NM</b>

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize <input type="checkbox"/> Deepen <input type="checkbox"/> Production (Start/Resume) <input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing <input type="checkbox"/> Fracture Treat <input type="checkbox"/> Reclamation <input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair <input type="checkbox"/> New Construction <input type="checkbox"/> Recomplete <input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans <input checked="" type="checkbox"/> Plug and Abandon <input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Convert to Injection <input type="checkbox"/> Plug Back <input type="checkbox"/> Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)



XTO Energy Inc. plugged & abandoned this well per the attached morning report.

3/13/07

RCVD MAR27'07

OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) <b>LORRI D. BINGHAM</b>		Title <b>REGULATORY COMPLIANCE TECH</b>
		Date <b>3/21/07</b>
<b>THIS SPACE FOR FEDERAL OR STATE OFFICE USE</b>		
Approved by	Title	Date <b>MAR 25 2007</b>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <b>FARMINGTON FIELD OFFICE</b>	

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

Morris, CM B #1 P&A MR.txt

3/6/07 Tstd anchors. SITP 45 psig. SICP 40 psig. SIBHP 15 psig. Bd well. MIRU A-Plus Rig #4. ND WH. NU BOP. Wkd tbg to 5K. Tbg parted. TOH & LD w/8 jts 1-1/4" LP. Tbg parted fr/pin. Fish w/col looking up. Virgil Lucero w/BLM on loc & witnessed operations.

3/7/07 SICP 45 psig. SIBHP 0 psig. Bd well. TIH w/OS, XO & 6 jts tbg. Tgd TOF @ 176'. Caught fish. TOH w/6 jts 1-1/4" IJ tbg, XO & OS, LD w/86 jts 1-1/4" LP. MIRU WLU. RIH w/3-1/2" GR to 1,944'. POH w/GR. RIH w/3-1/2" CIBP & set @ 1,944'. RD WLU. PU & TIH w/60 jts 1-1/4" IJ tbg. Tgd CIBP @ 1,944. Circ w/20 BFW. PT csg to 800 psig for 5". Tstd OK. Rlsd press. Plug #1 w/15 sxs Type III cmt (mixed @ 14.8 ppg, 1.32 cu ft/sx yield, 19.8 cu/ft). Ppd dwn tbg w/4.0 bbls cmt. Cmt fr/1,944' to 1,539'. TOH & LD w/26 jts tbg. TOH w/34 jts tbg. Perfd 3 sqz holes @ 1,165' w/1-11/16" strip gun. POH w/strip gun. RD WLU. Ppd dwn csg & EIR @ 2 BPM & 200 psig. Circ fr/csg vlv. RIH w/3-1/2" CICR & set @ 1112'. TIH w/stringer & 34 jts tbg. Sting into CICR @ 1,112'. Ppd dwn tbg & circ 2 bbls fr/csg vlv. SI csg vlv. Ppd dwn tbg. EIR @ 2 BPM & 600 psig. Opn csg vlv. Ppd dwn tbg w/10 BFW w/no rets fr/csg vlv. Plug #2 w/112 sxs Type III cmt (mixed @ 14.8 ppg, 1.32 cu ft/sx yield, 147.84 cu/ft). Ppd dwn tbg w/22.5 bbls cmt. Ppd dwn tbg w/16.1 bbls. Circ fr/csg vlv. Sting out fr/CICR. TOH w/2 jts. SDFN. Virgil Lucero w/BLM on loc & witnessed operations.

3/8/07 SICP 0 psig. SIBHP 0 psig. PT csg to 800 psig w/1 BFW for 5". Tstd OK. Rlsd press. RU WLU. RIH w/GR. Tgd TOC @ 795'. POH w/GR. Perfd 2 sqz hole w/1-11/16" strip gun @ 149'. POH w/strip gun. RD WLU. Ppd dwn csg. EIR @ 2 BPM & 800 psig w/45 BFW w/no circ fr/BH vlv. Ppd dwn BH w/3 BFW. Circ outside surf csg. Steve Mason approved ppg dwn csg w/100 sxs & allow cmt to fall. Plug #3 w/100 sxs Type III cmt w/2% CC (mixed @ 14.8 ppg, 1.32 cu ft/sx yield, 132 cu/ft). Ppd dwn csg w/20 bbls cmt. SD 2 hrs. PT csg to 800 psig w/1 BFW for 5". Tstd OK. Rlsd press. RU WLU. RIH w/GR. Tgd TOC @ 81'. POH w/GR. Plug 4 w/28 SXS Type III cmt (mixed @ 14.8 ppg, 1.32 cu ft/sx yield, 36.96 cu/ft). Ppd dwn BH w/5.6 bbls cmt. Circ good cmt fr/outside surf csg. ND BOP. RDMO A-Plus. SDFN. Steve Mason w/NMOCD contacted by phone. Virgil Lucero w/BLM on loc & witnessed operations.

3/13/07 Dig out WH. Cut off csg. Instd dry hole marker w/28 sxs Type III cmt. Cln loc. P&A is compld. Operations suspended until final cln up.