UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANGEMENT**

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Abandoned well. Use Form 3160-3 (APD) for such proposals.

If Indian, Allottee or tribe Name RCVD APR18'07

Lease Serial No.

NM = 013686

	7.	If Unit or CA/Agreement, Name and/or No.
URMIT IN TRIPIICATE - Other instructions on reverse side	l	OT COME DILL

	DIE VOIGI DEVI		
1. Type of Well Oil Well X Gas Well	Other	8. Well Name and No. Pritchard A 1A	
2. Name of Operator BP AMERICA PRODUCTION COMPANY		9. API Well No. 30-045-21792	
3a. Address P.O. Box 3092 Houston, Tx 77253-3092	3b. Phone No. (include area code) 281-366-7148	10. Field and Pool, or Exploratory Area Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Section 1 T30N R09W NWNW 1840' FNL & 1660' FWL		11. County or Parish, State SAN JUAN, NM	

12.	CHECK APPROPRIATE BOX	((ES) TO INDICATE NATU	RE OR NOTICE, REPORT, O	K OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume) Reclamation	Water shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

02/21/07 TOH W/ RODS AND PMP. SET PLUG IN F-NIPPLE, RIG DN WIRELINE, NIPPLE DN WELL HEAD, NIPPLE UP BOP'S. RU, PRESS TST BOP'S HIGH & LOW TST 1500/250 OK.

02/22/07 TOH W/ 2 3/8" TBG

02/23/07 RU ACID PMP TRUCK, PMP 1500 GAL, 15% HCL ACID, LET ACID SOAK ON PERFS FOR 1 HR. PMP 160 BBLS 2% KCL WTR DN TBG AND 60 BBLS 2% KCL WTR DN CSG. TOH W/ TBG.

02/24/07 LANDED TBG WITH KB @ 2876'. NIPPLE DN BOP'S

02/28/07 TST SEALS ON WELL HEAD TO 2500 PSI, HELD OK, HOLE W/ 2% KCL WTR AND PRESS TST TBG TO 500 PSI, TST OK.

14.	14. I hereby certify that the foregoing is true an dcorrect Name (Printed/typed)				
	Toya Colvin			Title Regulatory Analyst	
	Signature	Volla	Coli	Date 04/12/2007	

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the Office subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter witin its jurisdiction.