

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

NM - 010989

6. If Indian Allotment or Indian Name
207 APR 25 AM 11:16

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

7. If Unit or CA Agreement, Name and/or No.

RECEIVED
BLM
210 FARMINGTON NM

8. Well Name and No.

Fields A 20

9. API Well No.

30-045-27742

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

790' FNL & 790' FEL SEC 25 T32N R11W

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☐ Other

RCVD APR 26 '07

OIL CONS. DIV.

DIST. 3

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

4/6/07 TEST BOP RAMS & HYDRILL TO 100# LOW & 1000# HIGH, GOOD TEST

4/10/07 START UNIT, CK CSG PSI = 50#, TBG = 0#; PICK UP 94 JOINTS OF 2 3/8 TBG. PUMP 1500 GALLONS 15% HCL DOWN TBG TO BOTTOM OF PERFS. LAY DOWN 8 JOINTS OF TBG, WAIT ON ACID TO DO ITS JOB. RIG UP; PMP 10 bbls PRODUCED WTR DN TBG & PUMP 20 BBLs DOWN CSG, RIG Dwn. RIG UP; USE AIR/MIST - PUMP DOWN TBG TO CLEAN OUT ACID & WTR.; TAG PBTD, USE AIR TO CLEAN OUT TO 2985'

4/11/07 Land 2 3/8" tbg @2970', TST to 500 psi; held 5 min. good tst. TEST PUMP WITH RIG PUMP TO 500#, GOOD TEST

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature *Cherry Hlava*

Date 04/20/07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

APR 25 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD *by*