

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Abandoned well. Use Form 3160-3 (APD).

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.
NMSF- 078604-A

6. If Indian, Allottee or tribe

7. If Unit or CA/Agreement Name and/or No.

8. Well Name and No.
EALUM GAS COM


9. API Well No.
30-045-33486

10. Field and Pool, or Exploratory Area
Basin Dakota & Blanco Mesaverde

11. County or Parish, State
SAN JUAN, NM

SUBMIT IN TRIPLICATE - Other instructions on backside

RECEIVED
070 FARMINGTON NM



1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
BP AMERICA PRODUCTION COMPANY

3a. Address
PO BOX 3092 HOUSTON, TX 77253

3b. Phone No. (include area code)
281-366-3866

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1890' FNL & 2260' FEL; SEC 33 T32N R10W SWNE

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☐ Other DHC 2386AZ
8/28/06

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

5/2/07 TIH & LATCH ONTO BP @5070'. TOH w/BP.

5/4/07 TIH to 5300'; LATCH ONTO BP. TOH w/BP.

5/16/07 FLOW MV ON 3/4" CK PRESS 260# - FLR DRY GAS.

5/21/07 TIH MILL UP BP @ 7200'. CLEAN OUT TO PBDT @7448'.

5/23/07 TIH LAND 2 3/8", 4.7#, J-55 TBG @7312'

ALL 3 BRIDGE PLUGS DRILLED OUT & WELL IS DHC DAKOTA & MESAVERDE FORMATIONS.

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 05/23/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

MAY 30 2007

NMOCD

FARMINGTON FIELD OFFICE