## . UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

, ध्रमाह्या ।

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use APPLICATION				2 Lease Designation and Serial No.		
	TO DRILL" for permit for such proposals	Y		RECIGINATION Allottee or Tribe Name 記れ		
		2 10 FARY ROTON HM				
	· ·		7	If Unit or CA, Agreement Designation		
	SUBMIT IN TRIPLICATE					
1.	Type of Well		8	Well Name and No		
	Oil Well X Gas Well Other			ROSA UNIT #322A		
2	Name of Operator WILLIAMS PRODUCTION COMPANY		9.	API Well No. 30-039-29941		
3	Address and Telephone No PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL		
4	Location of Well (Footage, Sec., T., R., M., or Survey Description) 1945' FNL & 600' FWL, SW/4 NW/4 SEC 23-T31N-R05W		11.	County or Parish, State RIO ARRIBA, NM		
	CHECK APPROPRIATE BOX(s) TO INDICATE NAT	HRE OF NOTICE PED	∩RT 4	OR OTHER DATA		
	CILCRAT ROFIGATE BOX(S) TO INDICATE WAT	OKE OF NOTICE, KEI	OK1,	OR OTHER DATA		

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent  X Subsequent Report  Final Abandonment	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other <u>Drilling Complete</u>	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)			

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

<u>07-06-2007</u> MIRU, pick up Kelly mud motor & bit, mix spud mud. RU Yellow Dog pump, build volume, mix spud mud. Drlg 12 ¼" rat hole, lay out Kelly in V-door & tighten. Drlg 12 ¼" mouse hole.

<u>07-07-2007</u> LD mud motor, PU bell sub & shock sub. **Spud 12** ¼" hole @ 0830 hrs, 07/06/07. Drill 12 ¼" surface hole from 0' to 341' (TD surface hole @ 1530 hrs, 7/6/07. Circ & cond hole for 9 5/8" csg. TOOH LD shock & bell sub. RIH w/ 7 jts of 9 5/8", 36#, J-55, LT&C surface csg = 314' w/ float insert on top of 1<sup>st</sup> jt, set @ 326'. Circ csg, RD casers & RU cementers. Cmt 9 5/8" csg @ 326', shoe depth, single slurry cmt job, 10 bbls fresh water spacer, 185 sxs Type III cmt + 2% CaCl-2 + 1/4# Cello Flake + 30.81 bbl water = 48 bbl slurry @ 14.5 ppg. Displace w/ 21 bbl water, bump plug w/ 600# psi, PD @ 23:21 hrs. Check float, leaking, SI w/ 100 psi, 15 bbl cmt returns to surface (TOC on surface csg @ surface). RD cementers & WOC. Back out & LD 9 5/8" landing jt, make up well head, NU BOP & related equip.

07-08-2007 NU BOP, WO spacer spool, NU BOP, pressure test choke manifold, blind rams, pipe rams, & upper Kelly valve, 2000 psi high for 30 min, 250-psi low for 15 min & pressure test csg to 1500 psi for 30 min. All tested good. TiH w/ DC's. Kelly up & tag cmt. Drlg cmt & float equip, drlg from 341' to 408'. POOH LD DC's & PU directional tools.

_\_	Continued On Back		II CONS DIU	
14.	I hereby certify that the foregoing is true and correct			DIST. 3
	Signed Tracy Ross Tracy Ross	Title Sr Production Analyst	Date <u>July 24, 2007</u> .	ACCEPTED FOR RECORD
	(This space for Federal or State office use)		D	JUL 2: 5 2007
	Approved by  Conditions of approval, if any:	Title	Date	FARMENCTON FIELD OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

duplicate

07-09-2007 PU directional tools & SWDP. Directional drilling from 408' to 1020'.

Report hole size

07-10-2007 Directional drilling from 1020' to 1375'.

07-11-2007 Directional drilling from 1375' to 1766'. POOH to change bit fro slow ROP, make up new bit & add 8 1/4" stabilizer to BHA.

07-12-2007 TIH tag fill @ 1700'. Directional drilling from 1766' to 2175'.

07-13-2007 Directional drilling from 2175' to 2655'.

07-14-2007 Directional drilling from 2655' to 3068'.

<u>07-15-2007</u> Directional drilling from 3068' to 3142'. Circ & cond, POOH, tight hole 6 stds out, change bit & motor. Cut 250' of drlg line, RIH & tag @ 1700'. Kelly up, wash & ream, circ & cond raise vis to 76, wash & ream, RIH, Kelly up, wash & ream.

<u>07-16-2007</u> Wash & ream to bottom, circ & cond mud on bottom. Directional drilling from 3142' to 3593' (TD intermediate hole @ 0600 hrs, 07/16/07).

<u>07-17-2007</u> Circ & cond on bottom. POOH, chain out & strap out. LD directional tools, RIH, wash 120' to bottom, circ & cond on bottom. POOH, LD DP & HWDP, RU casers run 7" **guide shoe, 1 jt csg, 1 insert float, 78 jts csg, 23#, J-55, 8rd, LT&C, R3, MS csg = 3578.14' + 11.5' landing jt = 3589.64'. RD casers, land mandrel & WO cementers.** 

Report PT next report