

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an  
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED  
OMB No 1004-0135  
Expires November 30, 2000

5 Lease Serial No

**NMSF-080244**

6 If Indian, Allottee, or tribe Name

**2007 AUG -9 AM 11: 29**

7 If Unit or CA/Agreement, Name and/or No

**RECEIVED  
BLM**

8 Well Name and No **210 FARMINGTON NM**

**RIDDLE 1M**

9 API Well No

**30-045-33341**

10 Field and Pool, or Exploratory Area

**BASIN DAKOTA & BLANCO MESAVERDE**

11 County or Parish, State

**SAN JUAN, NM**

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1 Type of Well



Oil Well



Gas Well



Other

2 Name of Operator

**BP AMERICA PRODUCTION COMPANY**

3a Address

**PO BOX 3092 HOUSTON, TX 77253**

3b Phone No (include area code)

**281-366-4081**

4 Location of Well (Footage, Sec, T, R, M, or Survey Description)

**700' FNL & 2155' FWL; SEC 21 T30N R09W**

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION



Notice of Intent



Subsequent Report



Final Abandonment Notice

TYPE OF ACTION



Acidize

☐ Deepen



Production (Start/Resume)



Water shut-Off



Alter Casing



Fracture Treat



Reclamation



Well Integrity



Casing Repair



New Construction



Recomplete



Other Perf MV/ Straddle  
test for pressures



Change Plans



Plug and Abandon



Water Disposal



Convert to Injection



Plug Back

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

7/12/07 TIH pull 2 3/8" tbg. LD Tbg.

7/13/07 TIH set 4.5" CIBP @5500'. TIH shot 2 JSPF @ 5001', 4942', 4878', 4781', 4680', 4470', 4350'. TOH.

7/16/07- 7/25/07 Straddle pressure Testing MV perfs.

7/26/07 Pressure Test CIBP @5500' to 1500# charted O.K. Well shut in. Prepare for additional perfs & frac.

**RCVD AUG 16 '07  
OIL CONS. DIV.  
DIST. 3**

- 4 I hereby certify that the foregoing is true and correct

Name (Printed/typed)

**Cherry Hlava**

Title **Regulatory Analyst**

Signature

*Cherry Hlava*

Date **08/02/2007**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

**ACCEPTED FOR RECORD**

Approved by

Title

Date

**AUG 14 2007**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

**FARMINGTON FIELD OFFICE**

Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**MINCO** 8/20