Form 3160-5 (August 2007)

UNITED STATES

0V NOTIONS AND DEPOSITS ON THE
BUREAU OF LAND MANAGEMENT
DEPARTMENT OF THE INTERIOR

FC	RM APPROVED	•
ON	IB No. 1004-0137	
Evi	ires: July 31, 201	

5. Lease Serial No.

NM 9523

SUNDRY	NOTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
abandoned well.	Use Form 3160-3 (APD) for such proposals.

SUNDRY NOTICES AND Do not use this form for propo abandoned well. Use Form 3160	6. If Indian, Allottee or Tribe Name 707 AUG - 9 AM 1:		
SUBMIT IN TRIPLICATE -	Other instructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.	
. Type of Well		210 TARMINGTON NM	
Oil Well Gas Well Other		8. Well Name and No. Dome Federal 17-27-13 #3	
2. Name of Operator Maralex Resources, Inc.		9. API Well No. 30-045-23403	
a. Address	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area	
P. O. Box338, Ignacio,CO 81137	(970)563-4000	WAW Fruitland Sand PC	
Location of Well (Footage, Sec., T.,R.,M., or Survey Desc	cription)	11. Country or Parish, State	
90 FSL: 1560 FEL ection17-T27N-R13W		San Juan County, NM	
12. CHECK THE APPROPRIA	TE BOX(ES) TO INDICATE NATURE OF NO	OTICE, REPORT OR OTHER DATA	

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
Thomas of missin	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Subsequent report	Change Plans	Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
B. Describe Proposed or Completed	Operation: Clearly state all pertine	ent details, including estimat	ted starting date of any proposed wor	k and approximate duration thereof

13 the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Maralex Resources, Inc. intends to plug and abandon the Dome Federal 17-27-13 #3 well within the next few months. Work procedure as follows.

- 1. Rig up workover rig or coiled tubing unit.
- 2. Clean out to 1474'.
- 3. Spot 57 sacks cement plug from PBTD to surface.
- 4. Cut off well 6' below surface
- 5. Backfill and errect abandoned well marker.

RCVD AUG 23'07 OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (PrintedTyped) Jeremy Golob Titl	e Senior Petroleum Engineer
Signature D. Jeny Polis Date	. 08/07/2007
THIS SPACE FOR FEDERA	OR STATE OFFICE USE
Approved by Original Signed: Stephen Mason	AUG Z C 2007
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction