

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
**Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.
NMSF-078863

6. If Indian, Allottee or Tribe Name

RECEIVED

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

SEP 05 2007

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

8. Well Name and No.
Krause 22S

DEPT OF LAND MANAGEMENT
Farmington Field Office

2. Name of Operator
M & G Drilling Company

9. API Well No.
30-045-32495

3a. Address
PO BOX 5940, FARMINGTON NM 87499

3b. Phone No (include area code)
505-325-6779

10. Field and Pool or Exploratory Area
Basin Fruitland Coal

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SEC 28, T28N, R11W

11. Country or Parish, State
SAN JUAN

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Completion
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)


3/28/07 Schlumberger ran GR/CCL Logs PBTD 1941' ran rigless. 8/13/07 Perf 1789'-1827' w/48 JSPS. 8/14 A/Perfs 1789'- 1827' w/500 gals.15% HCL Acid 8/15 Frac w/40,000# SCF. Started Frac blowback @ 11:15 am @ 650 psi. 8/15 MIRU @ 12:40pm. 8/16 PU and ran 57 jts 2-3/8" 4.7# J-55 EUE 8rd tubing set @ 1816.33. 8/21 ND BOP. & RD. 8/21/07 Turned well over to production.

RCVD SEP 7 '07
OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)
Rhonda DeVilbiss

Title Production Assistant

Signature 

Date 09/05/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

SEP 06 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE
BY 

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD 