

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
**Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No
NO-G-0402-1710

6. If Indian, Allottee or Tribe Name
NAVAJO NATION

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other DRY HOLE

2. Name of Operator
NAVAJO NATION OIL & GAS CO., INC.

3a. Address
PO BOX 4439
WINDOW ROCK, AZ 86515

3b. Phone No. (include area code)
(928) 871-4880

7. If Unit of CA/Agreement, Name and/or No.
N/A

8. Well Name and No
HAWK 32-N-1

9. API Well No
30-045-33580 33850

10. Field and Pool or Exploratory Area
WC DES CRK, ISMAY, & LEADVILLE

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

538 FSL, 1553 FWL, SECTION 32, T32N, R19W, NMPM

11. Country or Parish, State
SAN JUAN, NEW MEXICO

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection)

WE PROPOSE TO PLUG AND ABANDON WELL AS FOLLOWS:

1. SPOT CEMENT PLUGS 7262-7112 (MISSISSIPPIAN), 6176-6026 (PARADOX/ISMAY), 5255-5105 (HONAKER TRAIL), 3620-3470 (WHITE RIM), 2290-2140 (CHINLE), 1744 TO SURFACE (ENTRADA/DAKOTA).
2. INSTALL DRY HOLE MARKER.
3. CLEAN LOCATION

RCVD SEP 26 '07

OIL CONS. DIV.
DIST. 3

RECEIVED

SEP 24 2007

Bureau of Land Management
Farmington Field Office

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

CHALMER T BITSOI

Title ENGINEERING ASSISTANT

Signature

Chalmer T Bitsoi

Date 09/19/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

SEP 25 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

NMOCD 88