Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

UNITED STATES	FORM APPRO
TMENT OF THE INTERIOR	OMB NO. 1004
	Expires: July 31
AU OF LAND MANAGEMENT	5 Y C

	Expires:	July	31,	20
case Seri	al No.			

Lease Serial No.	
NMSF078868	

SUNDKY N	OTICES AND RE	EPURIS	5 UN W	ELL2
Do not use this	form for proposal	s to drill	or to re	-enter an
abandoned well.	Use form 3160-3	(APD) fo	or such p	proposals.

6.	If Indian	Allo	ttee or	Tribe N	lame

abandoned we	II. Use form 3160-3 (APE)) for such	oroposals.	6. 11	muian, Anouce	of The Name
SUBMIT IN TRI	PLICATE - Other instruc	tions on rev	verse side.	7. If	Unit or CA/Agr	eement, Name and/or No
Type of Well ☐ Gas Well ☐ Other				ell Name and No DOBE A 1).	
2. Name of Operator DUGAN PRODUCTION COR	Contact:	JOHN C ALI nder@dugan			PI Well No. 0-045-21872	
3a. Address P O BOX 420 FARMINGTON, NM 87499-0-	420	3b. Phone N Ph: 505-32	o. (include area code 25-1821) 10, 1 C	Field and Pool, o UERVO GAL	r Exploratory LUP
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. 0	County or Parish	, and State
Sec 29 T24N R8W SENW 198 36.28725 N Lat, 107.70656 W				s	AN JUAN CC	DUNTY, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	E NATURE OF N	NOTICE, REPOR	T, OR OTHE	R DATA
TYPE OF SUBMISSION			TYPE O	FACTION		
Notice of Intent	☐ Acidize	□ Dec	epen	Production (S	tart/Resume)	☐ Water Shut-Of
_	Alter Casing	□ Fra	cture Treat	Reclamation		☐ Well Integrity
☐ Subsequent Report	Casing Repair	□ Nev	w Construction	Recomplete		Other
Final Abandonment Notice	Change Plans	⊠ Plu	g and Abandon	☐ Temporarily A	Abandon	
	Convert to Injection	□ Plu	g Back	☐ Water Disposa	al	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for final Plan to plug well as follows: Set CIBP @ 5000'. Spot 150' plug 15 sx Type 5 con Perforate @ 2700'. 2510' Spot 250' plug inside & outside Perforate @ 1722'. 1673' Spot 200' plug inside & outside Perforate @ 1950'. #02' Spot 250' plug inside & outside Perforate @ 253'. Pump type 5 cement w/3% call perforate @ 253'.	ement at 5000'. e casing. 65 sx Type 5 cere casing.	ment w/3% coment w	eacl2. (2520 - eacl2. (1402 - e to surface.	2420) 1578') 1302')	RCVD OGT OIL CONS DIST	, and the operator has 16 '07 . DIV.
Name (Printed/Typed) JOHN C A	For DUGAN PRO LEXANDER	DUCTION C	DRP, sent to the I	Farmington RESIDENT		
John CA	ELAMBLI		THE VICE-P	COIDLINI		
Signature (Electronic S	dubmission)	···	Date 10/04/2	007		-
	THIS SPACE FO	R FEDER	AL OR STATE	OFFICE USE		
Approved by - 7	M		Title PE			0¢10405 2007
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office (=0	U		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #56637 that would not fit on the form

32. Additional remarks, continued

Install dry hole marker & cut off anchors.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment	to	notice	of
Intention to	Ab	andon	:

Re: Permanent Abandonment

Well: 1 Adobe A

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Mesaverde plug from 2520' 2420' inside and outside the 5 1/2" casing.
- b) Place the Pictured Cliffs plug from 1678' 1578' inside and outside the 5 1/2" casing
- c) Place the Fruitland plug from 1402' 1302' inside and outside the 5 ½" casing.
- d) Place the Kirtland/Ojo Alamo plug from 1090' 827' inside and outside the 5 1/2" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.