و، چه					
In Lieu of Form 316 (June 199	0 DEPARTMI	TED STATES ENT OF INTERIOR AND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993	
Do not u	SUNDRY NOTICE AND se this form for proposals to drill or to deepen of	REPORTS ON WELLS or reentry to a different reservoir. Use "APPLICATION"	5.	Lease Designation and Serial No. NMSF-078768	
	TO DRILL" for perm			6 If Indian, Allottee or Tribe Name RCVD NDV 7'07	
	SUBMIT IN T	TRIPLICATE — CHIPO	7.	If Unit or CA, Agreement Designation ROSA UNEIL CONS. DIV.	
1	Type of Well Oil Well X Gas Well Other	RECEIVED NOV 0 2 2007	8	Well Name and NOST. 3 ROSA UNIT #375A	
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	insmenent.	9.	API Well No. 30-039-29704	
3.	Address and Telephone No. PO BOX 3102 MS 25-4, TULSA, OK 74101	Familiyon	10.	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL	
4.	Location of Well (Footage, Sec., T., R., M., or 895' FNL & 660' FWL, NW/4 NW/4 SEC		11.	County or Parish, State RIO ARRIBA, NM	
	CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR	OTHER DATA	
	TYPE OF SUBMISSION	TYPE OF ACTION			
	Notice of Intent	Abandonment Recompletion		Change of Plans New Construction	
	X Subsequent Report Final Abandonment	Plugging Back Casing Repair Altering Casing Other <u>PUMP REPAIR</u>		Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)	
13.	directionally drilled, give subsurface locations	Clearly state all pertinent details, and give pertinent dates, ir and measured and true vertical depths for all markers and	ncluding es I zones pe	stimated date of starting any proposed work. If well	
pump, fi open. 4 w/ tbg &	t rig & equip @ the Rosa #347A & roa Il tbg w/ wtr, press test tbg @ 900# so 40# csg, bled to FB tank recovering h	ad to location. NU w/ MO-TE & install 2 rig and blid test. ND w/ pump jack & horse head. Uns neavy wtr ret. ND w/ xmas tree, NU w/ BOP fu bg, junked out. MU w/ 4 3/4" bit, seat nipple w/	eat pun	np, TOOH w/ rods & pump, pump stuck est same. NU w/ work platform, TOOH	
TOOH w bph air/s TOOH w Space p	sg, BD to FB tank, killed w/ form wtr. v/ ret SV. ND w/ SL equip. TDH w/ tb soap/corrosion inhibitor, unable to circ v/ drill assy, TIH w/ prod assy, chem li	NU w/ Little Red overshot, TIH w/ same on 9/g & bit. Tagged top of fill @ 3572' = 13' fill pb: down w/ air. NU w/ PS, circ & drld from 3572 ne top 7 jts. Land OA @ 3563'. ND w/ BOP, oked to 500 w/ rig. NU w/ pump unit, hung on	td @ 35 2' to 357 NU w/ p	685'. NU w/ air pack. Break circ w/ 10 '9' = PBTD. Circ w/ soap sweeps. rod head, TIH w/ new pump & rods.	
14.	I hereby certify that the foregoing is true and c	orrect			
	Signed Kachel Lipperd	/	oate	October 30, 2007 .	
	(This space for Federal or State office use)				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, neithious of fraudulent statements or representations as to any matter within its jurisdiction.

Title


Approved by

Conditions of approval, if any:

NGV 0 6 2007

Date _

ROSA UNIT #375A BASIN FRUITLAND COAL



Open hole from 6-1/4" to 9-1/2" from 3369' to 3586'

PBTD @ 3585' TD @ 3586'

Hole Size	Casing	Cement	Volume	Top of Cmt	
12-1/4"	9-5/8", 36#	181 sxs	255 cu ft.	Surface	
8-3/4"	7", 23#	475 sxs	966 cu.ft.	Surface	
6-1/4"	5-1/2", 17#	Did Not Cmt	200000000000000000000000000000000000000		

RML 10/30/07