

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
Abandoned well Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No 1004-0135
Expires November 30, 2000

5 Lease Serial No
NM- 013686

6 If Indian, Allottee or tribe Name
RCVD DEC 17 '07

7 If Unit or CA/Agreement, Name and/or No
OIL CONS. DIV.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1 Type of Well
☐ Oil Well ☒ Gas Well ☐ Other DEC 13 2007

8 Well Name and No
DIST. 3
Pritchard 6E

2 Name of Operator
BP America Production Company Attn: Cherry Hlava Bureau of Land Management
Farmington Field Office

9 API Well No.
30-045-26149

3a Address
P.O. Box 3092 Houston, TX 77253

3b Phone No. (include area code)
281-366-4051

10 Field and Pool, or Exploratory Area
Blanco Pictured Cliffs

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)
1065' FNL 900' FWL Sec 34 T31N R09W

11 County or Parish, State
San Juan, NM

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water shut-Off

☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity

☐ Casing Repair ☐ New Construction ☐ Recomplete ☒ Other T&A Status;
Pressure Monitoring Well

☐ Change Plans ☐ Plug and Abandon ☐ Water Disposal

☐ Convert to Injection ☐ Plug Back

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

On Dec. 16, 1992 a bridge plug was set @3200' over the Dakota perms. and Dakota was T&A'd. The BP is still in the hole @3200'.

On 8/7/07 BP requested permission to T&A said well & turn into a pressure monitoring well. Approval was granted 8/14/07.

Subsequent sundry was submitted on 10/2/07 showing pressure test data with chart attached but neglected to report MIT was run and well is in T&A status.

Please accept this sundry for clarification purposes. Above mentioned well meets current T&A requirements as noted and approved on previous sundry dated 10/2/07. Well is currently being utilized as a Pictured Cliffs pressure monitoring well and is in T&A status.

OCS TA status expires 9/26/2012

14 I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 12/12/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

DEC 14 2007

OPERATOR

FARMINGTON FIELD OFFICE