UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVE	D	
OM B No 1004-0137		
Expires March 31	2000	

5 Lease Senal No

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		SF0771			
		6 If India	n, Allottee or Tribe Name		
			RCVD JAN 15 '08		
SUBMIT IN TRIPL	ICATE- Other instructions of	n-reverse side.	7 If Unit o	r CA/Agreement, Name and/or No OIL CONS. DIV.	
Oil Well Ga	as Well Other	IAN 9 2008	8 Well Na		
2 Name of Operator WEST LARGO (CORP.	JAN Department		ell No. 1	
3a. Address 8801 S. Yale Ave., Suite 240 Tulsa, OK 74137-3535 WEST LARGO CORP. 3b. Phone No (include area code) office 918-492-3239 Phone Property of the Pr		30-045 10 Field ar	ad Pool, or Exploratory Area		
4 Location of Well (Footage, Sec , T , R , M , or Survey Description)			Fruitland Coal		
1985' FNL, 2385' FWL, (SENW) Section 15, T28N, R9W, NMPM		11 County or Parish, State			
	,		San Ju	an, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF ACTION			
Notice of Intent ✓ Subsequent Report ☐ Final Abandonment Notice	Acidize Deepen Alter Casing Fracture T Casing Repair New Con Change Plans Plug and A	struction Recomplete Abandon Temporarily A	bandon	Water Shut-Off Well Integrity Other Logging, Production Csg MIT, Fracture	
	Convert to Injection Plug Back	Water Disposal		Treatment	
Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 11/6/07 MIRU BlueJet Logging @ 8:00 AM. GIH w/ logging tool, tag PBTD @ 2349'. Ran Gas Spectrum Log (GSL) and Cement Bond Log (CBL) from TD to surface. Top of cmt @ 180'. RDMO BlueJet @ 12:00 noon. 11/29/07 Antelope delivered & NU 4-½" frac valve. Press test valve & csg to 3,800#, held OK for 30 min. 12/4/07 MIRU BlueJet Logging & Key Energy @ 1:00PM. Perforate with HSC gun from 2155-70', 2209-14', 2217-20', 2222-24', 2263-82', (1 SPF), 44 total perfs. NU Key Energy pump truck, acidize perfs w/ 750 gals 7.5% HCl, breakdown perfs at 600#. Drop 66 ball sealers, pump acid @ max rate of 6 bpm, complete ball off, max press 3,400#. GIH w/ ring gauge and junk basket, tag PBTD @ 2352'. COH w/ junk basket, recovered 66 ball sealers, count 44 good hits. SI WH, RDMO Key & BlueJet @ 4:00 PM. 12/5/07 Ready to flow back after Frac treatment. MIRU Key Energy @ 7:00 AM. Spearhead 250 gals 7.5% HCl ahead of initial pad. Frac treatment of Fruitland Coal commenced at 10:15 AM. Pumped gelled wtr Nitrogen foam with 20/40 Brady Sand proppant: Avg. Treating Rate: 42 BPM Total Fluid pumped: 892 bbls Total N2: 1,408,744 scf Total Sand: 250,420 lbs ISIP: 1,378# Flowing thru 3/16" choke at 325 psig = 273 Mcfd. Flowing back gas & N2, no apparent wtr.					
14 Thereby certify that the foregoin Name (Printed/Typed) John P. Zarrett	g is true and correct	Title President			
Signature		Date	01/07/2008		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
	ed Approval of this notice does not warra]	Date	
certify that the applicant holds legal or education which would entitle the applicant to condition	quitable title to those rights in the subject le luct operations thereon	ease Office			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction					

(Instructions on page 2)

NMOCD (1)

ACCEPTED FOR RECORD

FARMANCTON FIELD OFFICE