Form approved. Budget Bureau No. 1004-0135

November 1983)	UNITED STA		BMIT IN TRIPLICATE ther Instructions on re	Expires Augus	
Formerly 9-331)	DEPARTMENT OF TH			5. LEASE TESIGNATIO	N AND BERIAL NO.
	BUREAU OF LAND MA	NAGEMENT- CAT	VER	See Attacl	hment
SUI (Do not use the	6. IN INDIAN, ALLOTT	EE OR TRIBE NAME			
1.		0312313	ELECTRIC STATE OF THE STATE OF	7. UNIT AGREEMENT N	2 KA
OIL GAS WELL	OTHER	i i e erice i i	った からと 真葉長春	West Bisti	į
2. NAME OF OPERATOR		FARMAN TON		S. FARM OR LEASE NA	ME
Chevron U.S	.A. Inc., Room 13097	ו בו הח	PEINEM		
3. ADDRESS OF OPERATO		107 ES 4		9. WELL NO.	
P. O. Box 59	99. Denver CO 80201			See Attach	nment
4. LOCATION OF WELL ( See also space 17 be At surface	MAR - 1 1932	OIL	CON. DIV.) DIST. 3	Bisti Lowe  11. BEC., T., B., M., OR  SURVEY OR ARE.  See Attach	er Gallup RLK. AND
14. PERMIT NO. CIL CONSERVATIONOSIVE OF Whether Dr. RT. GR. etc.)				12. COUNTY OR PARISI	1
	SANTA FE			San Juan	New Mexico
16.	Check Appropriate Box To	Indicate Nature of			
NOTICE OF INTENTION TO:			ECBSEQ!	GENT REPORT OF:	
TEST WATER SHUT-	OFF PULL OR ALTER CASIN	3 WA	TER SHUT-OFF	REPAIRING	WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRA	CTURE TREATMENT	ALTERING C	ABING
SHOOT OR ACIDIZE	ABANDON*	986	OOTING OR ACIDIZING	ABANDONME	NT*
REPAIR WELL	CHANGE PLANS	(01	her)		
(Other) Well Status X (Note: Report results of Completion or Recomplete					
				4 -1	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting engapproposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) \*

Chevron U.S.A. Inc. requests a one year extension of the long-term status for the wells listed in the table attached. More time is necessary to evaluate the pilot waterflood expansion installed in 1988. The expansion pilot waterflood outlined in the sundry dated December 9, 1987, was anticipated to become operational in the First Quarter of 1988, but did not become operational until almost the Third Quarter of 1988 due to delays. Some encouraging signs have been seen from this increased water injection, but more time is needed to determine if this expansion will be economic. In addition, we are evaluating the Coal Seam Methane potential of the acreage in the West Bisti Unit. Fruitland Coal does exist and is untested. We are currently reviewing the operating agreement to determine the method of testing the non-unitized coal beds with a currently shut-in unit well.

By the end of the Second Quarter 1989, we will submit a sundry outlining our plans for a Fruitland Coal test. We would like to understand the Coal Seam Methane potential better before abandoning these unit wellbores. By the end of the Fourth Quarter 1989, we will submit a sundry outlining the results of the waterflood expansion pilot. If the pilot was determined not to meet economic standards and no upper hole potential is determined to exist, then plans will be submitted at that time to start plugging wells in the First Quarter 1990. If the waterflood expansion is determined economic, then plans for a revamp will be submitted at that time.

· ·	,			TO DOE OND COULD OF SHEET THE STATE OF STATE OF SHEET THE SHEET OF SHEET		
18. I hereby certify that the foregoing is true and corre		Technical Assistant	_ DATE _	2-13-89		
(This space for Federal or State office use)			A	PPROVED		
APPROVED BY	TITLE _	,		AMENDED		

\*See Instructions on Reverse Side NMOCC

Sundry Notices and Reports on Wells West Bisti Page 2 February 13, 1989

Lease No.	Well No.	Well Type	Location	Sec., T, R Elevation
14-20-603-735-A	100	Oil Producer	1,980' FNL, 1,980' FEL	13-26N-14W 6357
NM-013492	102	Oil Producer	1,980' FSL, 1,165' FWL	18-26N-13W 6463
NM-013492	103	Oil Producer	660' FSL, 660' FEL	18-26N-13W 6312
NM-013492	109	Oil Producer	1,980' FNL, 660' FEL	20-26N-13W 6376
NM-013492	118	Oil Producer	660' FSL, 660' FEL	20-26N-13W 6380
SF-078091	121	Oil Producer	660' FNL, 1,980' FWL	29-26N-13W 6572
SF-078091	128	Oil Producer	1,980' FNL, 660' FWL	28-26N-13W-/28 6320
SF-078091	132	Oil Producer	1,980' FSL, 660' FEL	28-26N-13W- 34 6231
01 070031	1340	Oil Producer	1,980' FSL, 660' FEL	27-26N-13W-57 6198
SF-081028-A	136	Oil Producer	660' FSL, 1,978' FEL	26-26N-13W-136 6205
SF-078155	146	Oil Producer	660' FNL, 1,980' FWL	35-26N-13W - 46 6221
SF-078155	154	Oil Producer	1,980' FSL, 660' FEL	35-26N-13W -154 6233
SF-078155	159	Oil Producer	660' FSL, 1,980' FEL	35-26N-13W-159 6169
SF-078155	161	Oil Producer	600' FNL, 600' FEL	1-25N-13W 6179
SF-078155	162	Oil Producer	1,880' FNL, 1,980' FEL	1-25N-13W 6218
SF-078155	165	Oil Producer	660' FSL, 1,980' FEL	1-25N-13W-65 6239
Water will	149	0il Producer	2,310' FNL, 1,650' FEL	35-26N-13W <i>_149</i> 6230
SF-078155	153	Injector	1,990' FSL, 1,960' FWL	35-26N-13W-153 6237
SF-078091	131	0il Producer	2,200' FSL, 1,400' FEL	28-26N-13W-/*/ 6210
SF-078091	138	Oil Producer	990' FSL, 990' FEL	27-26N-13W-/3% 6209