

SOUTHERN UNION PRODUCTION COMPANY

WELLS REQUIRING FILE CORRECTION ONLY

LEASE NAME & WELL NUMBER	LOCATION	POOL	PRESENT ACREAGE	CORRECT ACREAGE
Jicarilla G #3	C-1-26N-5W	Tapacito PC	160	159.88
Foster #4	G-4-26N-8W	Basin Dak.	N 320	N 321.20
Davis #1	G-5-26N-8W	Ballard PC	160	160.79
Navajo Indian #6	E-6-26N-8W	Basin Dak.	W 320	W 323.03
Newsom B #8	P-6-26N-8W	Basin Dak.	E 320	E 320.57
Navajo Indian #2	D-19-27N-8W	So. Bl. PC	160	160.68
Navajo Indian B #4	D-30-27N-8W	So. Bl. PC	160	160.60
Navajo Indian B #5	L-30-27N-8W	Blanco MV.	W 320	W 320.80
Navajo Indian B #5	L-30-27N-8W	Basin Dak.	W 320	W 320.80
Navajo D #1	F-1-27N-13W	Basin Dak.	W 320	W 319.91
Richardson #1	A-2-27N-13W	Basin Dak.	E 320	E 319.79
Richardson Com #3	N-2-27N-13W	Basin Dak.	W 320	W 319.61
Congress #5	G-34-29N-11W	Basin Dak.	E 320	E 321.58
Congress #6	M-35-29N-11W	Basin Dak.	S 320	S 317.60
Calloway #1	A-3-30N-11W	Aztec PC	160	160.10
Haynie #1	G-4-30N-11W	Aztec PC	160	160.15
Federal #1	M-18-30N-12W	Basin Dak.	S 320	S 319.08
Reid A #1	A-1-30N-13W	Basin Dak.	E 320	E 319.70
Reid A #2	L-1-30N-13W	Basin Dak.	W 320	W 319.10
McCord #7	H-4-30N-13W	Basin Dak.	E 320	E 320.60
Teel #1	H-13-31N-9W	Blanco MV.	E 320	E 316.87
Seymour #3	B-24-31N-9W	Blanco MV	E 320	E 319.37
Trigg #1	N-25-31N-9W	Blanco MV	W 320	W 317.48