Form 31	60-5
(August	1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000



SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 5. Lease Serial No. SF-078425

6. If Indian, Allottee or Tribe Name

ノ 	abandoned well. Use form 3160-3 (APD) for such propos	FIVEN
	SUBMIT IN TRIPLICATE - Other instructions on reversi	Side.

1. Type of Well 2. Name of Operator

SAN JUAN 29-7 UNI

**SAN JUAN 29-7 UNIT 128** 

7. If Unit or CA/Agreement Name and/or No.

**BURLINGTON RESOURCES OIL & GAS** 

9. API Well No. 3003923777

8. Well Name and No.

3401 EAST 30TH 3a. Address FARMINGTON, NM 87402

which would entitle the applicant to conduct operations thereon.

3b. Phone No.(include area code) 505.326.9727 10. Field and Pool, or Exploratory Area **BASIN DAKOTA** 

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

11. County or Parish, and State RIO ARRIBA NM

1820FWL 1620FSL

K-27-29-7

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<ul><li>□ Notice of Intent</li><li>☑ Subsequent Report</li><li>□ Final Abandonment Notice</li></ul>	Acidize  Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	□ Water Shut-Off □ Well Integrity □ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be files within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

(5-2-01) MIRU. ND WH. NU BOP. TIH, tag up @ 8117'. TOOH w/252 jts 1 1/2" tbg. SDON.(5-3-01) TIH w/bit. Spot acid over Dakota interval. Blow well & CO to PBTD @ 8152'. TOOH. TIH w/3 7/8" bit to 8110'. Pump 500 gal 15% HCl into Dakota interval. Displace w/18 bbl wtr. Blow well & CO. TOOH w/bit. SDON.(5-4-01) TIH w/257 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 8066'. (SN @ 8033'). ND BOP. NU WH. Blow well & CO. RD. Rig released.

Electronic Submission #4070 verified by the BLM Well Information System for BURLINGTON RESOURCES OIL & GAS Sent to the Farmington Field Office Committed to AFMSS for processing by Maurice Johnson on 05/11/2001 Name (Printed/Typed) PEGGY COLE REPORT AUTHORIZER Signature 05/07/2001 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or FARMINGTON FILL certify that the applicant holds legal or equitable title to those rights in the subject lease Office