

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Bureau of Land Management
Farmington Field Office

JUN 12 2008

FORM APPROVED
OMB No 1004-0135
Expires July 31, 2010SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.

Lease Serial No

SF 078926

6 If Indian, Allottee or tribe Name

7 If Unit or CA/Agreement, Name and/or No

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well☒ Gas Well☐ Other

8 Well Name and No

Gallegos Canyon Unit 325

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

9 API Well No

30-045-24627

3a Address

P.O. Box 3092 Houston, TX 77253

3b Phone No (include area code)

281-366-4081

10 Field and Pool, or Exploratory Area

W. Kutz Pictured Cliffs

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1520' FNL & 880' FWL SEC 35 T29N R13W SWNW

11 County or Parish, State

San Juan County, New Mexico

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Water Disposal☐ Water shut-Off☐ Well Integrity☒ Other Compliance well

RCVD JUN 16 '08

OIL CONS. DIV.

DIST. 3

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

5/30/08 Spot in equipment. ND WH & NU BOP. RU floor, tongs. Test BOP OK

6/2/08 CSG 0 PSI; TIH w/4.5" CSG scraper & set @1567', load hole w/wtr; RU & test to 500 PSI. BLM satisfied with CSG test. RD. TOH w/Tbg. RU & run CBL 1567' - surface. Good bond except from 400' up; BLM satisfied with CBL. Allowed to continue with plugging program as submitted.

6/3/08 Spot 1st plug 40 sxs class G cement 1567' - 1013'; Density 15.60 ppg; Yield 1.180 cuft/sk. TIH set CIBP @500'. 2nd plug 38 sxs class G cement 500' - surface; Density 15.60 ppg; Yield 1.180 cuft/sk. ND BOP; Top off cement to surface.

6/5/08 Cut off old well head; Weld on dry hole marker. Rig down; turn over for reclamation work.

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature *Cherry Hlava*

Date 06/09/2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

JUN 13 2008

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

NMOC