submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVE

AUG 1 8 2008

bureau of Lano Managemeni

		Farmington Field Office
Sundry Notices and Reports on Wells		The Office
	5.	Lease Number
		USA – SF-080668
1. Type of Well	6.	If Indian, All. or
GAS		Tribe Name
2 N 60 A	7.	Unit Agreement Name
2. Name of Operator BURLINGTON		
RESOURCES OIL & GAS COMPANY LP		San Juan 27-4 Unit
	8.	Well Name & Number
3. Address & Phone No. of Operator	0.	, , , , , , , , , , , , , , , , , , , ,
		San Juan 27-4 Unit 139N
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
		30-039-30438
4. Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
Surf: Unit B (NWNE), 110' FNL & 1700' FEL, Section 9, T27N, R4W, NMPM	10.	Basin DK/Blanco MV
BH: Unit A (NENE), 800' FNL & 710' FEL, Section 9, T27N, R4W, NMPM		
2	11.	County and State
		Rio Arriba Co., NM
Notice of Intent Abandonment Change of Plans X Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		RCVD AUG 27'08 OIL CONS. DIV.
Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		
13. Describe Proposed or Completed Operations		DIST. 3
See sundry dated 8/14/08 for details of intermediate casing and production casing fishing, See NOI date 8/2/08 With AWS 184, RU cementers to set plugs. 1st plug @ 6284' cemented w/22 bbls cement. Plug cement. 2nd plug pumped 15 bbls cement for 300' plug from 5078' – 5378'. Reversed out excess cement 4403' – 4677', reversed out excess cement. POOH. 8/3/08 RIH w/bit & reamed cement to 4435'. PT Circ. well. TOH & LD bit & reamer. RU WL & RIH & set CIBP @ 4415'. RD WL. RIH w/whipstoc to azimuth of 195 degree: TOP of WS 4400', window @ 4408'. RD WL. Milled window to 4413'. LI	g @ 5700' ent. PU & casing to 1 k to 4253'	- 62 84'. Reversed out excess set 3 rd plug w/12 bbls cement @ 500# 15 min prior to TOH. RIH w/WL orient whipstock
8/4 Drilled 6-1/4" hole (sidetrack) to TD @ 8648". TD reached 8/12/08. Circ. hole. RIH w/100 jts 4-1/w/TOL @ 4384". RU to cement. Pumped preflush of 10 bbls mudclean and 2 bbls FW ahead of 10 sx 3 (614 cf – 109 bbls) Premium Lite High Strength FM w/3% CD-32, .25#/sx Cellophane Flakes, 1% FL-5 FW w/10 bbls containing 25# sugar). Bumped plug w/932 #. RD BJ. Ran WL survey w/gyro data. Nl	Scavenger 52, 6.25#/s:	(31cf - 5.5bbls). Tailed w/310 sx x LCM-1. Displaced w/134 bbls o
Will report TOC and casing PT on the next report. PT will be conducted by the completion rig.		
NOTE: The gyro indicated that the hole deviated into a non-standard (NSL) location. We will be completed this well. \checkmark	filing for	NSL approval before we
14. I hereby certify that the foregoing is true and correct.		
Signed Title Regulation	ılatory Sı	pecialist Date 8/18/08.
(This space for Federal or State Office use)		ACCEPTED FOR RECORD
APPROVED BYTitle		Date ALIC 2 5 2000
CONDITION OF APPROVAL. if any:		MUU Z J 2008
Fitle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or transdulent statements or representations as to any matter within its jurisdiction.	MOCD	FARMINGTON FIELD OFFICE