

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Girard Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-031-20433
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	SANTA FE PACIFIC
8. Well Number	113
9. OGRID Number	185239
10. Pool name or Wildcat	CHACO WASH MESAVERDE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
ENERDYNE LLC

3. Address of Operator
P.O. BOX 502, ALBUQUERQUE, NM 87103

4. Well Location
Unit Letter P 165 feet from the SOUTH line and 965 feet from the EAST line
Section 21 Township 20N Range 9W NMPM County MCKINLEY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
6418' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-12-03

RIG UP OVER WELLBORE-RAN 10 JTS. OF 2 3/8" TUBING TO TD.
CIRCULATED WELLBORE WITH FRESH WATER AND POLYMER DISPERSANT.
SPOTTED 55 GALLONS OF 12% HCL ACID WITH 5% WETTING AGENT AT TD.

6-13-03

CIRCULATED WELLBORE CLEAN OF SPENT ACID, TREATED WITH POLYMER, PULLED TUBING & RIG DOWN.

6-14-03

RAN SUBMERSIBLE PUMP IN WELLBORE HUNG ON 1/4" STAINLESS STEEL CABLE TIED OFF TO WELLHEAD AND 5/8" PE TUBING. SET SURFACE ELECTRICAL EQUIPMENT AND FENCED LOCATION.
WELL READY TO PRODUCE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE GENERAL MANAGER DATE 10-24-03

Type or print name DON L. HANOSH E-mail address: DHanosh426@aol.com Telephone No. 1-505-332-7807

(This space for State use) DEPUTY OIL & GAS INSPECTOR, DIST. 00 NOV - 7 2003

APPROVED BY [Signature] TITLE DATE

Conditions of approval if any: