Submit 3 Copies To Appropriate District Office	State of New Me	xico	Form C-103
District I	Energy, Minerals and Natu	ral Resources	Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240		WELL API NO	
<u>District II</u> 1301 W. Cirand Ave , Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-031-05406
District III	1220 South St. Fran	5. Indicate Type STATE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM-87		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM		20 × 1	Clas Dease 140.
87505			
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name	or Unit Agreement Name
(IX) NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"	LS TO DRILL OR TO DEFEED OR FLU TION FOR PERMIT" (FORM C-101) FO	R SUCH SAN	ITA FE PACIFIC
PROPOSALS.)	ÇÜ ,		
1. Type of Well:	(cc.	8. Well Number	#3
Oil Well 🛛 Gas Well 🔲 C	Other Signal Control of the Control		#3
2. Name of Operator	- 110 X25	9. OGRID Nu	
ENERDYN	Na 51	212 02 61 (1)	185239 '
3. Address of Operator P.O. BOX 502, ALBUQUERQUE, NM 87103 10. Pool name or Wildcat CHACO WASH MESA VERDE			or Wildcat
P.O. BOX 502, ALBUQUERQUE, NM 87103 CHACO WASH MESA VERDE			WASH MESA VERDE
4. Well Location			
77 77 77 78	330 feet from the SOUT	гы 660 с	handle FACT Une
Unit Letter P:	feet from the SOU	H line and feet f	from the <u>EAST</u> line
Section 21	Township 20N I	tange 9W NMPM	County MCKINLEY
	11. Elevation (Show whether DR.		County
	6405' G		
12. Check An	propriate Box to Indicate N	ature of Notice, Report or Oth	er Data
NOTICE OF INT		SUBSEQUENT R	
	PLUG AND ABANDON	REMEDIAL WORK	
TEN ON THE PERIOD E TOTAL	. EGG AND ABANDON []	TEMESIAE TOTAL	, ALTERNITO GROWING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND
			ABANDONMENT
	MULTIPLE COMPLETION	CASING TEST AND	
	COMPLETION	CEMENT JOB	
OTHER:		OTHER:	
13 Describe proposed or complet	ed operations. (Clearly state all n	ertinent details, and give pertinent de	ites, including estimated date
		e Completions: Attach wellbore dia	
or recompletion.	,		g
·			
MAY 27, 2003:			
REMOVED SURFACE EC			
RIG UP OVER WELLBOR	RE-RAN 10 JTS. OF 2 3/8"	TUBING TO TD.	
CIRCULATED WELLBORE WITH FRESH WATER AND POLYMER DISPERSANT.			
SPOTTED 55 GALLONS OF 12% HCL ACID WITH 5% WETTING AGENT AT TD.			
		TETTING AGENT AT TE.	
MAY 28, 2003:	- 01 - 11 0 = 0 = 11 1 1 0 = = = 1		
CIRCULATED WELLBOR	E CLEAN OF SPENT ACID, T	REATED WITH POLYMER,PUL	LED TUBING & RIG DOWN.
MAY 29, 2003:			
•	AP IN WELL BORE HUNG ON	1/4" STAINLESS STEEL CABLE	TIED OFF TO WELL HEAD
•		QUIPMENT AND FENCED LOCA	ATION.
WELL READY TO PRODU			
I hereby certify that the information about	ove is true and complete to the be	st of my knowledge and belief.	
hat I	^	OFNEDAL MANAGED	10.24.02
SIGNATURE AND A. Na. 4	TITLE	GENERAL MANAGER	DATE 10-24-03
Tune or print name DON L. HANC	SH E	hdress: DHanosh426@aol.com	Telephone No. 1-505-332-7807
Type of print name	E-mail a	udiess:	AICH.
(This space for State use)	_//		MOV - 7 2003
APPPROVED BY have	7 FTTT 103Pl	ITY OIL & GAS INSPECTOR, DIST.	¹
Conditions of annroyal if any	111LE		- 90