007	4 6	2000	FORM APPROV		
UUI	CT (2 2008	OMB No 1004-0			

Form 3160- 5	UNITED STA	ATES	OCT	പ്ര ഉസ	FORM APPROVE	ED	
(August, 2007)	DEPARTMENT OF T	HE INTERIOR	UUT	<b>(2</b> 2008	OMB No 1004- 01	137	
	BUREAU OF LAND M	ANAGEMENT			Expires July 31, 20	010 -	
			ا المام المساوية المام الم المام المام ال	5 Lease Serial l	Ņo		
SUNDRY NOTICES AND REPORTS ON WELLS					NM-013642		
	not use this form for proposal doned well. Use Form 3160-3			6. If Indian, Allo	ottee, or Tribe Name		
	TRIPLICATE - Other Instruc	ctions on page 2.		7 If Unit or CA	. Agreement Name a	nd/or No.	
1. Type of Well				8 Well Name a	4 NT-	_	
Oil Well X Gas Well	Other			well Name al	na No	•	
2 Name of Operator	Gard		C5				
Coronado Energy E & P Compan	y, LLC	<del></del>	<del></del>	9 API Well No.	•		
3a Address		3b. Phone No. (incli	o. Phone No. (include area code)			. 20.045.22054	
1099 18th Street, Suite 1900 Denver, CO 80202		303.2	291.6400	30-045-32054 10 Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Sec., T., R	, M, or Survey Description)	Lat.	36.95261	-	or, or Employment,		
1680'	1010'			11 County or Pa	arish, State	, ., .,	
SW SE FSL	FWL 26 T 32N R 9	9W Long.	-107.75471	San J	uan	NM	
12. CHECK APPROPE	RIATE BOX(S) TO INDICATE	NATURE OF NO	TICE, REPORT, O	R OTHER DA	ТА	-	
TYPE OF SUBMISSION		Т	YPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production ( S	tart/ Resume)	Water Shu	t-off	
	Altering Casing	Fracture Treat	Reclamation		Well Integ	rity	
Subsequent Report	Casing Repair	New Construction	X Recomplete		X Other		
	Change Plans	Plug and abandon	Temporarily A	bandon	Clean Out		
Final Abandonment Notice	Convert to Injection	Plug back	Water Dispos	al			
13. Describe Proposed or Completed	Operation (clearly state all pertinent	details including estin	nated starting date of	any proposed wo	ork and approxima	te duration thereof.	
	ectionally or recomplete horizontally, work will performed or provide the						
	ed operations If the operation result						
•	Abandonment Notice shall be filed	only after all require	rements, including recl	amantion, have be	een completed, and	d the operator has	
determined that the site is ready for fir	al inspection )				RCVD OC	T7'03	
1. MIRU. Install & Test B						i.DIV.	
2. PU tbg. Tag fill. POOH		\$10° 42° 410° 420°	G.				
3. PU mill & work string and clean out to PBTD.  4. PU 5-1/2" csg spear, jars, collar - attempt to pull liner. If liner comes free, POOH LD liner.							
	e - release csg spear & POOl			nici.			
6. PU 2-3/8" tbg and run la	9 2	II LD Hannig too.	13.				
7. Remove BOP's	anding at + 3100.						
8. Run Rods & Pump.	n						
9. RDMO. Install pumping	r Unit DOD						
7. KDMO: Instant pumping	g Omt. I Of						
				,			
				•			
14 I hereby certify that the foregoing is tr Name ( <i>Printed/Typed</i> )	ue and correct	1				_	
Pachael Overhou		Title		Enginogrin	a Took	•	

14 I hereby certify that the foregoing is true and correct Name (Printed/ Typed)							
Rachael Overbey		Engineering Tech					
Signature (Aachael Vuhe	Date	9/30/2008					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Original Signed: Stephen Mason	Tıtle	Date OCT 0 3 2008					
Conditions of approval, if any are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon							
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2)	NWI	OCD A					