In Lieu of Form 3160 (June 1990)

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

NOV 2 0 2008

FORM APPROVED Budget Bureau No. 1004-0135

AU OF LAND MANAGEMENT

SUNDRY NOTICE AND I Do not use this form for proposals to drill or to deepen or TO DRILL" for permit		or reentry to a different reservoir. Use "APPLICATION			
				If Indian, Allottee or Tribe Name	
	SUBMIT IN T	RIPLICATE	7.	If Unit or CA, Agreement Designation ROSA UNIT	
1.	Type of Well		8.	Well Name and No.	
	Oil Well X Gas Well Other			ROSA UNIT #229	
2.	Name of Operator		9.	API Well No.	
	WILLIAMS PRODUCTION COMPANY		_	30-039-24496	
3	Address and Telephone No.		10.	Field and Pool, or Exploratory Area	
	PO BOX 3102 MS 25-4, TULSA, OK 74101 (918) 573-3046			BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T., R.,		· · · · · · · · · · · · · · · · · · ·		County or Parish, State	
	1865' FSL, 1055' FWL, NW/4 SW/4, SEC 29, T31N, R05W		<u> </u>	RIO ARRIBA, NM	
	CHECK APPROPRIA	IE BOX(s) TO INDICATE NATURE OF NOTICE, RI	PORT, OR	OTHER DATA	
	TYPE OF SUBMISSION		OF ACTION	ON	
R	Notice of Intent	Abandonment Recompletion		Change of Plans New Construction	
	X Subsequent Report	Plugging Back		Non-Routine Fracturing	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Casing Repair

Altering Casing

Ξ Other __PUMP REPAIR

11-03-2008

RU FB tank, SITP=0, SICP=340#, BD to FB tank, RU unit, floor on unit to big, hits A-legs on pump jack, RD floor, had smaller floor brought out f/ town, RD head off pumping unit, chg pump on rig pump not working, got pump primed up, press test tbg 700#, lost 400# in 5 min, unseat pump and reseat, press to 800#, lost 180# 3 min, bleed off press, unseat pump and POOH w/ rods, 1.25" PR X 22' X 1.5" X 10' liner, 2' X 3/4" pony rod, 4' X 3/4 pony rod, 129 - 3/4" rods, 2.5" X 1.25" pump, , ND B-1 adapter, NU BOPE, RU floor, change over to pull tbg, secure well, SDFN.

CONTINUED ON ATTACHED SHEET:

Final Abandonment

RCVD NOV 25'08 OIL COMS. DIV. DIST. 3

(Note: Report results of multiple completion on Well Completion or Recompletion Report

Water Shut-Off

Dispose Water

and Log form.)

Conversion to Injection

14.	I hereby certify that the foregoing is true and correct Signed Rachel Lipperd	Title Engineering Technician II	Date	November 17, 2008
	(This space for Federal or State office use)			NOV 2 1 2008
	Approved by	Title		Date
	Conditions of approval, if any.			FARIHOTON FIELD OFFICE


11-04-2008

SITP=340#, SICP=340#, BD to FB tank, unable to RU tongs, don't have long enough pins or bolts, wait on mechanic to repair rig floor, repair floor and tongs, TOOH tally 2 7/8" 6.5# J-55 eue tbg, 10' pup, 2 - 6' pups, 103 jts, 2.28" SN, mud anchor = 3270.54', TIH w/ 4 3/4" bit, c/o 3' of fill w/ 12 bph mist to PBTD @ 3287', circ clean, TOOH w/ 4 3/4" bit, TIH w/ mud anchor, 2.28 F-N, 10 stands, secure well, drain up equip, SDFN.

11-05-2008

PJSM, finish TIH w/ prod. Tbg, RU SBS, band 1/4" chem inj line to last 242' of tbg, land 2 7/8" 6.4# J-55 EUE tbg as follows top down w/ KB corr: 1 jt, 10' pup, 6' pup, 6' pup, 102 jts, 2.28" F-Nipple @ 3253', orange peeled MA @ 3282', perfs 3108'-3287', ND BOPE, NU B-1 adapter, RIT w/ 2.5"X1.25"X10X14 RHAC pump, 129 - 3/4" rods, 4' pony, 2' pony, 1.25"X22' PR X 1.5"X10' liner, seat pump, load tbg w/ prod water and test to 500 psi 15 min, good test, bleed press to 300 psi, stroke pump and press to 500 psi 5 min, good test, bleed off press, set tag, hang rods on unit, RD pump, pit, air package, to windy to RD unit, will Rd in morning, rel. rig to RU#206A.

ROSA UNIT #229 BASIN FRUITLAND COAL



-	Hole Size	Casing	Cement	Volume	Top of CMT
	12-1/4"	9-5/8", 36#	160 sx	109 Cu. Ft.	Surface
	8-3/4"	7", 20#	660 sx	1109 Cu. Ft.	Surface
	9 1/2"	5-1/2", 17#	None	N.A.	N.A.