Form 31	60-5
(August	2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO 1004-0135 Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an Delly Delly abandoned well. Use form 3160-3 (APD) for such proposals.			NMNM113426 6 If Indian, Allottee or Tribe Name			
			OCT A	0.000	_	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agre	ement, Name and/or No.
		E	Ureau of I	2 × m		,
1 Type of Well Gas Well O	: 8 Well Name and No OJO ENCINO 21 FEDERAL 1H					
2. Name of Operator Contact: ARTHUR (BUTCH) W BUTLER HIGH PLAINS OPERATING COMPANE-Mail: bbutler@highplainsop.com					9 APT Well No. 30-031-21107-00-X1	
3a. Address 32700 ASPEN DRIVE BUENA VISTA, CO 81211	3b. Phone No (include area code) Ph: 719-395-8059 Fx: 719-395-8093			OJO		
4 Location of Well (Footage, Sec., T, R, M., or Survey Description)				11. County or Parish, and State		
Sec 21 T20N R5W NESW 2537FSL 2523FWL 35.94893 N Lat, 107.37144 W Lon					MCKINLEY COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	DINDICATE	NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
- Notice of Intent	☐ Acidize	□ Dec	pen	□ Produc	tion (Start/Resume)	☐ Water Shut-Off
Nonce of Intent	Notice of Intent Alter Casing Fracture Treat		ture Treat	— Reclan	nation	☐ Well Integrity
Subsequent Report	Casing Repair	n Nev	v Construction	_		Other
1 0		g and Abandon	_	emporarily Abandon Drilling O		
0	Convert to Injection	□ Plu _Ł		□ Water		
If the proposal is to deepen direction Attach the Bond under which the wifollowing completion of the involve testing has been completed. Final Adetermined that the site is ready for High Plains Operating Compa	ork will be performed or provide d operations. If the operation re bandonment Notices shall be fil final inspection.)	the Bond No. o. sults in a multipled only after all ting with Bond	n file with BLM/B le completion or re requirements, incl	SIA. Required su ecompletion in a luding reclamation	ibsequent reports shall be new interval, a Form 316	filed within 30 days 60-4 shall be filed once
HPOC RESPECTFULLY REG	QUESTS THAT ALL INFO			LL BE HELD	CONFIDENTIAL.	
The well was spudded at 19:30 hrs on 9/22/09 with United Drilling Rig 29. A 12-1/4" hole was drilled to 445 prior to running sfc csg. See previously submitted sundries for 9 5/8" sfc csg and						
7" csg details.V					_ ne c	MS.DIV.
On 10/08/09, the 7" csg was tested after cementing to 1850 psi and held for 5 minutes. See BJ Chart that follows, showing slight increase in pressure during hold period. Good test.						
Reached a TD of 7595' MD, 8	5909.48' TVD on 10/18/09.	See accom	panying final s	urvey informa		
INADEQUATE PRE	SSURE TEST ON 7"	CASING -	SEE NMOCE	PULE 19	15,16,10,I -S	SUBJUIT RE-TEST
14. Thereby certify that the foregoing	is true and correct. Electronic Submission # For HIGH PLAINS O mmitted to AFMSS for proc	76331 verified PERATING CO essing by TR	by the BLM W MPANY, sent DY SALYERS o	ell Information to the Farming n 10/29/2009 (n System gton 10TLS0011SE)	
Name (Printed/Typed) ARTHUR	5		Title MANA			
Signature (Electronic	Submission)		Date 10/27	/2009		
	THIS SPACE FO	OR FEDERA	L OR STATI	E OFFICE L	JSE	
Approved By ACCEPT			TROY S Title PETROL	ALYERS EUM ENGIN	IEER	Date 10/29/200
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

RETEST 7" CASING TO MEET REQUIREMENTS OF NMOLD RULE 19.15.16.10. I NMOCD₁₀₀

Additional data for EC transaction #76331 that would not fit on the form

32. Additional remarks, continued

Bottom of lateral appears to be in Entrada water zone. Set cement plug 7595' MD to 7330' MD. Halliburton pumped 60 sx class G cement w/ 3% KCL, 0.2% Halad R-344, 0.2% HR-5, 0.3% CFR-3. Density 17.0 ppg, yield 1.0 cu/ft sk. Pumped 5 bbls diesel w/ MUSOL ahead. Displace w/ 68.9 bbls OBM to balance plug.

On 10/21/09, ran 4 1/2" predrilled liner. Ran 34 jts 4.5" J-55, 11.6# LT&C casing total 1528.63'. Ran 1 guide shoe 2.45', 34 jts casing 1528.63', J Lock hanger 2.46', retrievable setting tool 1.75', 94 stds drill pipe + 16.30' of 1 single in. Total 5910.58'. Landed @ 7445.87' MD, pulled out w/ setting tool & drill pipe. Top of hanger is @ 5912.33' MD w/ 178.67' overlap in the 7" casing. The drop sleeve looking up is 6.125" OD, 4.938" ID.

United Drilling Rig 29 released at 6:00 PM on 10/22/09. J

16