

Form 3160-5
(September 2001)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

MERRION OIL & GAS CORPORATION

3a. Address

610 Reilly Ave., Farmington, NM 87401

3b. Phone No. (include area code)

(505) 327-9801

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 1650' FWL

SECTION 20, T26N, R11W

5. Lease Serial No.

SF-078899A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement, Name and/or No.

DHC 1303A2

8. Well Name and No.

BLACKROCK D COM No. 1

9. API Well No.

30-045-05776

10. Field and Pool, or Exploratory Area

GALLEGOS GALLUP

11. County or Parish, State

SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX (ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Casing repair☐ New Construction☐ Recomplete☒ Other☐ Change Plans☐ Plug and Abandon☐ Temporarily Abandon

COMMINGLING

☐ Final Abandonment Notice☐ Convert to Injection☐ Plug Back☐ Water Disposal

PROGRESS REPORT

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final insection.)

11/5/03 Found well on vacuum. TIH, tag up on cement at 2688'. Pressure test casing to 500 psi, lost 70 psi in 15 mins. TOH, PU bit, bit sub and RIH on 6 each 3-1/8" drill collars and 2-3/8" tubing. Tag up on cement at 2688'. PU power swivel and break circulation with water. Drill out cement down to 2854'. Circulate hole clean pull up to 2800'. Drain pumps and lines. SWI, secure location. SDON.

11/6/03 TIH continue drilling cement. Drilled out cement down to 3100'. Circulate hole clean with 2% KCl. RUTS. Will start swabbing for "dry test" in morning. SWI, secure location and SDON.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

STEVEN S. DUNN

Title DRILLING & PRODUCTION MANAGER

Signature

Date November 17, 2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the application holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD

FARMINGTON FIELD OFFICE

IEG 29 2003