UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**



	Sundry Notices and Reports on Wells	DEC 2	? 1 2009
		The special control of the second of the sec	
		[-a. 12. 5. 5. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6.	Lease Nümber SF-047017-B
1.	Type of Well GAS	6	. If Indian, All. or Tribe Name
2.	Name of Operator	7	. Unit Agreement Nam
۷.	BURLINGTON		
	RESOURCES OIL & GAS COMPANY LP		. Well Name & Numbe
3.	Address & Phone No. of Operator	O	Angel Peak B 30
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9	. API Well No.
4.	Location of Well, Footage, Sec., T, R, M		30-045 -24530
			0. Field and Pool
UIII	it B (NWNE), 790' FNL & 1800' FEL, Sec. 13, T28N, R11W, NMPM		Otero Chacra
		1	1. County and State San Juan Co., NM
			·
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOT Type of Submission Type of Action	TICE, REPORT, OTHE	ER DATA
		Change of Plans	Other - BH repair KGR0928842797
	·	New Construction Non-Routine Fracturing	
		Water Shut off	
	Final Abandonment Altering Casing	Conversion to Injection	
	13. Describe Proposed or Completed Operations		
			RCVD JAN 7'10
			OIL CONS. DIV.
			DIST. 3
			Dist. o
See	e attached sheet for details		
I he	ereby certify that the foregoing is true and correct.		
Sign	ned Monda Rogers T	itle Staff Regulatory	Technician Date 12/1
	0		
	nis space for Federal or State Office use)		D .
	PROVED BYTitle NDITION OF APPROVAL, if any:		Date
Title I	18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of inited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		DEPTED FOR RECORD
			JAN 05 2010
	ĭ.	ra a	RAMATON FIELD OFFICE

Angel Peak B 30 API #30-045-24530

12/4/09 MIRU Aztec 746. 12/7/09 RIH & set CW plug @ 275' & RD HH. ND WH & NU BOP. RU slickline & pull CW plug @ 275'. RD slickline. 12/8/09 TIH w/mill tagged scale @ 2860'. CO scale from 2860' to PBTD @ 3024'. Circ clean. TOOH & LD tool.

12/9/09 RU slickline & RIH w/GR to tight spot @ 1400', work down to 1470' Set plug @ 287'. Load csg w/2% KCl H2O. PT to 500# communications to BH. Reset plug @ 157' & 27' re-test & had communications to BH @ both settings. Pulled test plug. RD slickline. NU BOP. Located hole in csg between 10' & 20'. ND BOP. RU slickline & set plug @ 1000'. Removed WH & filled w/water in BH & found TOC @ 11'.

12/10/09 Called Steve Mason (BLM) & Kelly Roberts (OCD) to report & verbal given to proceed w/pumping cmt down backside. Pumped cmt dn annulus between 7 5/8" & 2 7/8" csg , 8 sx (9.44 cf) Class C cmt. NU WH. WOC 12/11/09 Released/LD plug @ 1000'.

12/14/09 Attempt MIT & failed, but no pres or communication on BH. RIH & set plug @ 27'attempt to test csg, getting communication around pkr, pull to 22' & 17' continued to get communication around pkr. RU Phoenix & pulled plug @ 1000'. 12/15/09 Called Steve Mason (BLM) and he said tbg could be hung to 2860' @ CH & pkr screwed in @ 27' and then tbg screwed on and run to surf. Kelly Roberts & Charlie Perrin (OCD) was called and decision was made that hole needed to be fixed to prevent contamination going into formation.

12/16/09 Engineer made decision to P&A well. Steve Mason, Kelly Roberts and Charlie Perrin were informed. NOI w/procedures to P&A was submitted. 12/16/09 ND BOP & NU WH. RD & RR.